

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



Vecon.

DATE : 10.01.2022

TO : CHINA TAITING MOTOR CLAIMS DEPTS
VEHICLE NO : GBH3160K
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 08.01.2022
TIME OF ACCIDENT : 14:45HRS

KDH 2010230875

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SLIDING DOOR RH <i>Distorted</i>	1	\$ 1,650.00	\$ 1,650.00
2	SLIDING DOOR SWITCH CONNECTOR <i>Repl</i>	1	\$ 88.00	\$ 88.00
3	SLIDING DOOR STEP PANEL RH <i>Repl</i>	1	\$ 817.00	\$ 817.00
4	SLIDING DOOR LOWER RAILWAY PANEL RH <i>Repl</i>	1	\$ 946.00	\$ 946.00
5	SLIDING DOOR ROLLER (LOWER) RH <i>Centre Best</i>	1	\$ 317.00	\$ 317.00
6	SLIDING DOOR LOCK CATCHER RH <i>new</i>	1	\$ 26.00	\$ 26.00
7	SLIDING DOOR INNER LOCK RH <i>2nd</i>	1	\$ 522.00	\$ 522.00
8	SLIDING DOOR STOPPER (SET) <i>new</i>	2	\$ 27.00	\$ 54.00
9	SLIDING DOOR FRAME WEATHER STRIP RH <i>new</i>	1	\$ 331.00	\$ 331.00
10	SLIDING DOOR INNER BOARD RH <i>torn</i>	1	\$ 325.00	\$ 325.00
11	SLIDING DOOR GLASS RH <i>shattered</i>	1	\$ 1,280.00	\$ 1,280.00
12	SLIDING DOOR GLASS MOULDING RH <i>new</i>	1	\$ 181.00	\$ 181.00
13	REAR SIDE PANEL RH <i>Repl</i>	1	\$ 1,848.00	\$ 1,848.00
14	REAR SIDE PANEL MUDFLAP RH <i>new</i>	1	\$ 196.00	\$ 196.00
15	ROCKER PANEL RH <i>Repl</i>	1	\$ 388.00	\$ 388.00
16	REAR ALXE	1	\$ 1,989.00	\$ 1,989.00
17	REAR SHOCK ABSORBER RH	1	\$ 439.00	\$ 439.00
18	REAR WHEEL HUP RH	1	\$ 390.00	\$ 390.00
19	REAR WHEEL HUP BEARING RH	1	\$ 187.00	\$ 187.00
20	REAR STABILIZER BAR	1	\$ 436.00	\$ 436.00
21	REAR STABILIZER LINKAGE RH	1	\$ 160.00	\$ 160.00

3110

233250

SN: 780

TOTAL PRICE \$ 12,570.00
LESS 25% \$ 3,142.50
SUB TOTAL PRICE \$ 9,427.50

TO : CHINA TAITING MOTOR CLAIMS DEPTS
 VEHICLE NO : GBH3160K
 MODEL : TOYOTA HIACE
 DATE OF ACCIDENT : 08.01.2022
 TIME OF ACCIDENT : 14:45HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SLIDING DOOR INNER BOARD CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00 <i>30</i>
2	SLIDING DOOR GLASS SEALANT RH <i>nec</i>	1	\$ 80.00	\$ 80.00 <i>60</i>
3	SLIDING DOOR GLASS INNER SEAL RH <i>nec</i>	1	\$ 60.00	\$ 60.00 <i>40</i>
5	REAR SIDE PANEL SEALANT RH <i>new</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
6	REAR FLOOR PANEL TOP BOARD (SPECIAL TYPE) <i>torn</i>	1	\$ 850.00	\$ 850.00 <i>380</i>

510

TOTAL \$ 1,120.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>700</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>50</i>
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>x</i>
7	TRANSFER SLIDING DOOR MECHANISM RH	\$ 80.00	<i>✓</i>
8	REMOVE AND REFIX SLIDING DOOR GLASS RH	\$ 100.00	<i>60</i>
9	REMOVE AND REFIX REAR SIDE PANEL RAILWAY RH	\$ 80.00	<i>x</i>
10	REMOVE AND REFIX REAR SIDE PANEL GLASS RH	\$ 100.00	<i>x</i>
10	VACCUM AND CLEAN FRONT WINDSCREEN GLASS SPLINTER	\$ 380.00	<i>80</i>
12	REMOVE AND REFIX REAR WHEEL BEARING	\$ 60.00	<i>x</i>
13	FOUR WHEEL ALIGHMENT	\$ 120.00	<i>x</i>

TO : CHINA TAITING MOTOR CLAIMS DEPTS
VEHICLE NO : GBH3160K
MODEL : TOYOTA HIACE
DATE OF ACCIDENT : 08.01.2022
TIME OF ACCIDENT : 14:45HRS

14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	--	-----------	---

1760

TOTAL \$5,360.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,547.50
TOTAL LABOUR COST : \$ 5,360.00
TOTAL REPAIR COST : \$ 15,907.50

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

Adrian Lj
H/S 10/01/22.
05 Days.

total: 5382.50
H/S: A.31C

A.31C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: