

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9853E*Not Authored
Primary B4 print***AAD2201-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHD9853E

JTDKB3FU703093242

TOYOTA

PRIUS GEN 4

31/12/2021

To Kio

23/12/2020

11 JAN 2022

PART	LIST
1 COVER, FRONT BUMPER	\$ B 521.00 ✓
1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$ R 110.50 X
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$ R 716.60 X
1 ABSORBER, FRONT BUMPER ENERGY	\$ P 80.20 X
1 SUPPORT, FRONT BUMPER SIDE, RH	\$ P 80.10 ✓
1 EXTENSION, FRONT BUMPER, RH	\$ L 120.10 X
1 COVER, FRONT BUMPER HOLE, RH	\$ R 30.20 X
1 MOULDING, FRONT BUMPER SIDE, RH	\$ CM 95.60 ✓
1 GRILLE SUB-ASSY, RADIATOR	\$ P 422.50 X
1 GRILLE, RADIATOR, LOWER NO.1	\$ L 178.60 X
1 EMBLEM ASSY, RADIATOR GRILLE	\$ R 105.80 ✓
1 JAR ASSY, WINDSHIELD WASHER	\$ Rep 219.10 X
1 UNIT ASSY, HEADLAMP, RH	\$ M/C 2,637.60 ✓
1 FENDER SUB-ASSY, FRONT RH	\$ P 977.80 ✓
1 LINER, FRONT FENDER, RH	\$ P/L 202.50 ✓
1 EMBLEM, SIDE PANEL, RH	\$ R 54.60 ✓
1 JAR ASSY, WINDSHIELD WASHER	\$ R 219.10 ✓
1 HOOD SUB-ASSY	\$ R 983.10 X
1 HINGE ASSY, HOOD, LH	\$ R 58.90 X
1 HINGE ASSY, HOOD, RH	\$ R 58.90 X
1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$ M 100.40 ✓
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$ P 1,436.60 X
1 RIM	\$ R 1,900.10 ✓
TOTAL	\$ 11,309.90
25%	\$ 2,827.48
	\$ 8,482.43

Special Nett

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2201-

SHD9853E

- 1 TYRE
- 1 HUB CAP
- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1 FENDER LINER CLIP
- 1 FENDER CLIP

\$	pu 250	350.00	800.00
\$	nn	211.50	
\$	nn	95.00	500.00
\$	nn	85.00	X
\$	nn	65.00	
\$	nn	70.00	X
TOTAL	\$	806.50	

TOTAL PARTS	\$	9,288.93
--------------------	-----------	-----------------

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	500.00
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	nn 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	60.00
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	30.00
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	550.00

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2201-

SHD9853E

To reinstall rear bumper parking sensor.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	201
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	X
TOTAL	\$	8,670.00	
Over All Total	\$	17,958.93	

(PART-BY-PART) Repair Days**25 DAYS**

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: