

TP Chinn.
Asher.

SMF 311 S. 2018 Oct
BMW X1 1499 cc

WBAJG120503676526.

Rear Bumper	Del'd	1392 ✓
Rear Bumper Clips.	Nec	50(SN) ✓
Rear Bumper Side Holder x02	HP Nec	$135 \times 2 = 270$ X
Rear Bumper Lower Grinish	Del'd	368. ✓
Rear Bumper Reinforcement.	HP N	683 X.
Rear Bumper Centre Guide.	Could	195 ✓
Rear Bumper Tow Cover.	HP N	35 X
Rear Bumper Kick Sensor	HP N	398 X
Rear Bumper Reflector x02	HP N	$71 \times 2 = 142$ X
Reverse Sensor x 04	1 piece dnd	$265 \times 4 = 1060$ 265
Reverse Sensor Holder x 04.	Nec	$35 \times 4 = 140$ ✓

2360
2829

S.N. 50

SMF311S

Panel Benti

Spry Painting.

Wiring.

To spray tuff coat.

To perform diagnostic test.

To remove reverse sensor

~~400~~ 250

~~400~~ 350

690

~~50~~ 30

150 X

200 X.

100 60.

total: 2864

L/S: 2-BK

02 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2,300

2 days