

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 20 Jan 2022

Preliminary Advice

Vehicle No	: SJB6428G	Accident Date	: 24/12/2021
Make	: MERCEDES-BENZ A180	Policy No.	: 1700093733-04
Assignment Date	: 19/01/2022	Excess	: S\$0.00
Date of Inspection	: 13/1/2022	Est. Duration of Repair	: 18
Inspection At	: MOVA AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	53,517.95
Revised Amount	:S\$	38,486.85
Check Items (Estimated)	:S\$	14,671.80
Total	:S\$	53,158.65
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	43,896.00
Salvage Value	:S\$	
Margin for Repair	:S\$	59,104.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Pending for investigation

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .