



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2202160

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/04/2022
Reference CC3/CTI22000432/Gga3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 6998P
Insured Veh. GBF 2263P
Claim No. SNM22D200333
Policy No. DMCVSNW00085262100
Accident Date 09/01/2022
Inspection Date 11/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI22000432/Gga3q2 Date: 14/04/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 2263P	Veh. Inspected	SH 6998P	
Policy No.	DMCVSNW00085262100	Coverage (\$)	0.00	
Claim No.	SNM22D200333	Excess (\$)	0.00	
Assign From		Assign Date	11/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID 1.8	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU503556785	Colour	BLUE	
Odometer	491004 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/01/2022	Inspection Date	11/01/2022	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 6998P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TRUNK OUTER GARNISH	CRACKED	889.70	889.70
1	REAR TRUNK LID LOGO (PRIUS)	NECESSARY	60.80	60.80
1	REAR TRUNK LID LOGO (HYBRID)	NECESSARY	52.40	52.40
1	REAR TRUNK LID LOGO (TOYOTA STAR)	NECESSARY	52.90	52.90
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	REAR BUMPER LOWER COVER -BLACK	CUT	552.60	552.60
1	REAR BUMPER CTR UNDER COVER	NOT NECESSARY	552.60	-
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	112.70	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER LOWER EXTENSION RH	NOT NECESSARY	232.00	-
1	REAR BUMPER TOW COVER	CUT	82.70	82.70
1	TAILLAMP UPPER RH	NOT NECESSARY	557.90	-
1	TAILLAMP LOWER RH	NOT NECESSARY	548.40	-
	LESS 25% DISCOUNT		-1,123.53	-542.93
			3,370.57	1,628.77
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR TRUNK COMFORTDELGRO (SN)	NECESSARY	30.00	30.00
1	REAR TRUNK 65521111 (SN)	NECESSARY	30.00	30.00
1	REAR TRUNK APPS (SN)	NECESSARY	40.00	40.00
			235.70	100.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	350.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	WIRING CHARGE.	NOT NECESSARY	40.00	-
	TUFF KOTE.	NOT NECESSARY	40.00	-
	REMOVE/REFIX REVERSE SENSOR .		120.00	40.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TOWING FEE-CHIT ATTACHED.		60.00	60.00
			1,660.00	950.00
GRAND TOTAL			5,266.27	2,678.77
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,150.00

Report Ref No. CC3/CTI22000432/Gga3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 6998P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 6998P

RE-INSPECTION

