

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000441/KGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900077569
Claimant Vehicle No :	SKR6513Y	Insured Vehicle No :	SMK3118M
Date of Loss:	08/01/2022	Nature of Claim:	TP
		Claim No:	6309392562SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR6513Y	Engine No:	P520253994
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Chassis No:	JM6BM42A8F0166511
Reg. Date:	27/02/2015 (Man. Year: 2014)	Odometer:	89337 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Michelin 4 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,768.00	2,565.28	5,202.72	66.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,820.00	1,710.00	48.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,298.00	4,385.28	6,912.72	61.19
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	11,298.00	3,500.00	7,798.00	69.02
+ GST 7.00/7.00% (S\$)	790.86	245.00	545.86	69.02
Nett Amount (S\$)	12,088.86	3,745.00	8,343.86	69.02
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,052.45		
Global Sum Settlement (S\$)		4,050.00		

INSPECTION

Date of Assignment:	12/01/2022	Wei Lee Motor Works (HQ)
Date Inspected:	12/01/2022 Inspected At:	BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32
Estimated Period of Repair:	6.0 days	Singapore 575644

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	1,006.00 FL	*- FL
2	1		*TAILGATE LOCK	Repair	187.00 FL	*- FL
3	1		*TAILGAQTE -MAZDA LOGO	Necessary	77.00 FL	*77.00 FL
4	1		*TAILGAQTE -MAZDA EMBLEM	Necessary	54.00 FL	*54.00 FL
5	1		*TAILGATE -SKYACTIVE EMBLEM	Necessary	67.00 FL	*67.00 FL
6	2		*TAILGATE REFLECTOR	Serviceable	980.00 FL	*- FL
7	1		*TAILAMP	O/S Broken	1,734.00 FL	*790.60 FL
8	1		*SARE TYRE PANEL	Repair	551.00 FL	*- FL
9	1		*END PANEL	Repair	531.00 FL	*- FL
10	1		*END PANEL TOP GARNISH	Serviceable	168.00 FL	*- FL
11	1		*BOOT WEATHERSTRIP	Serviceable	119.00 FL	*- FL
12	1		*REAR BUMPER	Bent	947.00 FL	*947.00 FL
13	1		*REAR BUMPER ENFORCEMENT	Repair	565.00 FL	*- FL
14	1		*REAR BUMPER RETAINER	O/S Cracked	76.00 FL	*38.00 FL
15	2		*REAR BUMPER REFLECTOR	Serviceable	106.00 FL	*- FL
16	2		*REAR BUMPER TOW COVER	Serviceable	76.00 FL	*- FL
17	1		*REAR FENDER	O/S Bent	2,466.00 FL	*1,233.00 FL
					Sub Total (S\$)	9,710.003,206.60
					- List Item Discount on L Items 20.00/20.00% (S\$)	1,942.00641.32
					Total Parts (S\$)	7,768.002,565.28

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE /REINSTALL REAR WINDSCREEN GLASS	New	180.00	120.00
2	TO REMOVE INNER GARNISH ,REAR SPEAKER BOARD,ROOF LINING ENABLE REPAIR JOB CARRY OUT ,REINSTALL AFTER JOB DONE	New	250.00	100.00
3	TO REMOVE DAMAGED PARTS & ATTACHMENTS CUT & WELD DAMAGED PANEL ,FENDER STRAIGHTEN REAR CHASSIS WHERE NECESSARY REPLACE /ALIGN ALL PARTS INTO POSITION	New	1,500.00	800.00
4	TO SPRAY PAINT	New	1,600.00	800.00
Gross Labour Cost (\$\$)			3,530.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >