WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32, SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com NOT Norhairs

LIPM &

Revney After Paint

6day

Business Regn No: 269436/00J

11-JAN-2022

AIG ASIA PACIFIC INSURANCE PTE LTD 78, Shenton Way AIG Building #07-16 Singapore 079120

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SMK3118M Accident involving vehicle no: SKR6513Y/SMK3118M DOA: 08/01/2022 at ADAM ROAD BEF CAMDEN PARK

Dear officer in charge

Estimate cost of repair for vehicle no: SKR6513Y

To supplied:

Description		Qty		Amount	
Tailgate		1	N	1006.00	X
Tailgate lock	- 90	1	n	187.00	X
Tailgate – Mazda logo		1	Ma	77.00	
Tailgate – Mazda emblem		1	na	54.00	_
Tailgate – Skyactive emblem		1	na	67.00	_
Tailgate reflector		2	14	980.00	/
Tailamp	elsan	2		1734.00	4
Spare tyre panel		1	n	551.00	X
End panel		1	n	531.00	X
End panel top garnish		1	m	168.00	X
Boot weatherstrip		1	A	119.00	X
Rear bumper		1	Ry	947.00	
Rear bumper enforcement		1		565.00	X
Rear bumper retainer		2 C	sint		1-4
Rear bumper reflector		2	Sin	106.00	X
Rear bumper tow cover		2	Pm		K
Rear fender		2 0/		2466.00	1
			-	2400.00	
Parts				0740.00	
Parts less 20%	LKK Auto Consultants no	nce notify		9710.00	
1 4113 1633 2070	ine Repairer of the follow	una:		7768.00	
***************************************	 To resurvey before/after spra 	painting			
	To display damaged part(s) d Parts prices are subsected.	uring survey			
Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" base.			`		
	No illegal modification(s) is allowed				
Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company					

Acknowledged by Repairer

is subject to final approval from Insurance Company

Sagnaturo

Dale.

I REF. (11/ 27 11-11)

To remove/reinstall rear windscreen glass To remove inner garnish, rear speaker board, Roof lining enable repair job carry out, reinstall after job done To remove damaged parts & attachments Cut & weld damaged panel, fender Straighten rear chassis where necessary Replace /align all parts into position To spray paint

180.00 1201

250.00 10d

1500.00

1600.00

11,298.00