ERING PTE LTD

the Repairer of the following RESTIMATE

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

 Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed

Toyota Prius Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

INSURANCE: LONPAC (P)

MVA: LIM T S

VEHICLE NO.: SHA2258

DATE:

MODEL:

12-Jan-22

Acknowledged by Repairer

	Signature:				
PART NO.	DaleDESCRIPTION	QY	UNIT PRICE	AMOUNT	
	Rear Trunk Outer Garnish X Lyur			\$889.70]
	Rear Trunk Lid Logo (Prius)	1		\$60.80	
	Rear Trunk Lid Logo (Hybrid)	4 1		\$52.40	
	Rear Trunk Lid Logo (Toyota Star)	1		\$52.90	
	Rear Bumper / le	1		\$458.60	
	Rear Bumper Re-Inforcement	1		\$318.80	
	Rear Bumper Lower Cover-Black / CA	1		\$552.60	
	Rear Bumper Ctr Under Cover X C Rear Bumper Side Retainer RH X 7	1		\$552.60	
		1	\$112.70	\$112.70	
	Rear Bumper Clips / MC	10	\$2.20	\$22.00	
	Rear Bumper Reflector RH X	1		\$55.00	
	Rear Bumper Tow Cover	1		\$82.70	
	Taillamp Upper RH ?	1	\$557.90	\$557.90	
	Tailllamp Lower RH ?	1	\$548.40	\$548.40	
	0117 7074				
	SUB TOTAL	1		\$4,317.10	
	LESS 25%	I		\$1,079.28	J
1	DISCOUNTED TOTAL			\$3,237.83	
	Reverse Sensor X	1		£405.70	
	Rear Trunk ComfortDelGro / /			\$135.70	
	Rear Trunk ComfortDelGro Rear Trunk 65521111	li		\$30.00	
	Rear Trunk APPS			\$30.00 \$40.00	
		'		\$40.00	
	NETT TOTAL			\$235.70	
				\$235.70	1
	TOTAL SPARE PARTS			\$3,473.53	l
	Labour Charge			\$3,473.53	i
	Panel Beating			\$ 000.00	250
	Spray Painting Charge			\$800.00	350 500 7 X NN 40
	Wiring Charge			\$600.00	700
	Tuff Kote			\$40.00	1 %
	Remove/Refix Reverse Sensor			\$40.00	XW
	The same same same same same same same sam			\$120.00	40
	TOTAL LABOUR				77
	TOTAL LABOUR		[\$1,600.00	
	EQTIMATE TO				
	ESTIMATE TOTAL		[\$5,073.53	
This is an initial a	timate based on a visual issued in				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

10 mgs. Great photos. 12/1/22 2:30 m