

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G



Service Centre

limited Repair

not Authorised
 14/1/22
 2/5 # 4150
 5 days

ESTIMATED COST: HQQ000575

TO : LONPAC INSURANCE BHD.
ATTN : MOTOR CLAIM DEPARTMENT

SJE7925R**AFIDAH BINTE ALI**

BLK 896

TAMPINES STREET 81

#06-880

SINGAPORE,

SINGAPORE 520896

CONTACT NO : 96260220

DATE : 13-JAN-2022
 MAKE : TOYOTA
 MODEL : VIOS E AUTO
 CHASSIS NO : MR053HY9305061107
 ENGINE NO : 1NZX741496
 SERVICE ADVISOR : HAZEL
 PAGE : 1 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT BUMPER	DIS 483-30	599.90 ✓
1	FRONT BUMPER LH SIDE RETAINER	Bent 66-50	78.80 ✓
1	FRONT BUMPER LH SIDE BRACKET	n1	179.90 X
1	FRONT BUMPER REINFORCEMENT	n1	352.70 X
1	FRONT LH FENDER	DIS 388-50	850.95 ✓
1	FRONT LH FENDER INNER SHIELD	Torn 166-20	195.40 ✓
1	FRONT LH FENDER BRACKET	R	123.73 X
1	FRONT LH FENDER PANEL	Repeated	655.95 X
1	HEADLAMP LH	one 407-20	512.60 ✓
1	HEADLAMP BRACKET LH	n1	0.00 X
1	HEADLAMP INNER PANEL LH	R	165.40 X
1	FRONT LH DOOR	DIS	820.88 ✓
1	FRONT LH DOOR HINGE UPPER	tw1	98.70 ✓
1	FRONT LH DOOR HINGE LOWER	tw1	98.70 ✓
1	FRONT LH DOOR WEATHERSTRIP	new	175.60 ✓
1	FRONT LH DOOR BOARD	n1	678.75 X
1	FRONT LH INNER TRIM BOARD	n1	0.00 X
1	FRONT LH DOOR LOCK	n1	388.70 X
1	DOOR MOTOR REGULATOR	n1	175.85 X
1	B PILLAR	R	366.70 X
1	REAR LH DOOR	dis/Bent 811-10	890.90 ✓
1	REAR LH DOOR HINGE UPPER	tw1	98.70 ✓
1	REAR LH DOOR HINGE LOWER	tw1	98.70 ✓
1	REAR LH DOOR WEATHERSTRIP	new	175.60 ✓
1	REAR LH DOOR BOARD	n1	766.40 X
1	REAR LH DOOR LOCK	n1	378.70 X
1	REAR LH FENDER	R	1,033.75 X

(252)

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000575**

TO : LONPAC INSURANCE BHD.
ATTN : MOTOR CLAIM DEPARTMENT

SJE7925R
AFIDAH BINTE ALI
 BLK 896
 TAMPINES STREET 81
 #06-880
 SINGAPORE,
 SINGAPORE 520896
 CONTACT NO : 96260220

DATE : 13-JAN-2022
 MAKE : TOYOTA
 MODEL : VIOS E AUTO
 CHASSIS NO : MR053HY9305061107
 ENGINE NO : 1NZX741496
 SERVICE ADVISOR : HAZEL
 PAGE : 2 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	REAR LH FENDER INNER SHIELD <i>11</i>	89.40 <i>X</i>	
1	REAR LH FENDER BRACKET <i>11</i>	0.00 <i>X</i>	
1	REAR LH FENDER PANEL <i>Repetd</i>	0.00 <i>X</i>	
1	FRONT LH KNUCKLE ARM <i>11</i>	511.60 <i>X</i>	
1	FRONT LH KNUCKLE BREARING <i>11</i>	133.70 <i>X</i>	
1	FRONT LH LOWER ARM <i>11</i>	877.60 <i>X</i>	
1	FRONT LH LOWER ARM TIE ROD <i>11</i>	0.00 <i>X</i>	
1	FRONT LH STABILIZER BAR <i>11</i>	0.00 <i>X</i>	
1	FRONT LH STABILIZER LINKS <i>11</i>	187.60 <i>X</i>	
1	FRONT LH STABILIZER BUSHING <i>11</i>	45.70 <i>X</i>	
1	FRONT LH STEERING RACK <i>11</i>	221.45 <i>X</i>	
1	FRONT LH SHOCK ABSORBER <i>11</i>	366.80 <i>X</i>	
1	FRONT RH KNUCKLE ARM <i>11</i>	0.00 <i>X</i>	
1	FRONT RH KNUCKLE BREARING <i>11</i>	87.50 <i>X</i>	
1	FRONT RH LOWER ARM <i>11</i>	200.00 <i>X</i>	
1	FRONT RH LOWER ARM TIE ROD <i>11</i>	0.00 <i>X</i>	
1	FRONT RH STABILIZER BAR <i>11</i>	0.00 <i>X</i>	
1	FRONT RH STABILIZER LINKS <i>11</i>	187.60 <i>X</i>	
1	FRONT RH STABILIZER BUSHING <i>11</i>	47.50 <i>X</i>	
1	FRONT RH STEERING RACK <i>11</i>	179.90 <i>X</i>	
1	FRONT RH SHOCK ABSORBER <i>11</i>	272.90 <i>X</i>	
1	SIDE MIRROR LH <i>cur</i>	799.75 <i>X</i>	
1	SIDE MIRROR COVER LH <i>cur</i>	103.30 <i>X</i>	
1	SIDE MIRROR STAY LH <i>11</i>	49.60 <i>X</i>	
1	SIDE MIRROR SIGNAL LAMP LH <i>cur</i>	89.60 <i>X</i>	
Sub Total		14,413.46	0.00

SPECIAL NETT

1 FRONT LH RIM *cur* 600.00 *280 5/11*

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000575**

TO : LONPAC INSURANCE BHD.
ATTN : MOTOR CLAIM DEPARTMENT

SJE7925R
AFIDAH BINTE ALI
 BLK 896
 TAMPINES STREET 81
 #06-880
 SINGAPORE,
 SINGAPORE 520896
 CONTACT NO : 96260220

DATE : 13-JAN-2022
 MAKE : TOYOTA
 MODEL : VIOS E AUTO
 CHASSIS NO : MR053HY9305061107
 ENGINE NO : 1NZX741496
 SERVICE ADVISOR : HAZEL
 PAGE : 3 OF 3

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	FRONT RH RIM <i>cu7</i>	600.00	<i>280 s/n</i>
10	FRONT BUMPER CLIPS <i>ner</i>	50.00	<i>✓ s/n</i>
10	HEADLAMP CLIPS <i>11</i>	50.00	<i>X</i>
10	FRONT FENDER INNER SHIELD LH CLIPS <i>ner</i>	50.00	<i>✓ s/n</i>
10	REAR FENDER INNER SHIELD LH CLIPS <i>11</i>	50.00	<i>X</i>
Sub Total		1,400.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	1,800.00	<i>800</i>
1	TO SPRAY PAINT ON AFFECTED AREAS	2,000.00	<i>1200</i>
1	TO APPLY UNDERCOATING FOR RUST PROOFING	180.00	<i>> 90</i>
1	TO APPLY TUFF COAT ON AFFECTED AREAS	150.00	<i>50</i>
1	TO DISMANTLE, REPLACE AND/OR REPAIR FRONT LH DOOR COMPONENTS	150.00	<i>50</i>
1	TO DISMANTLE, REPLACE AND/OR REPAIR REAR LH DOOR COMPONENTS	150.00	<i>50</i>
1	TO CHECK WIRING	120.00	<i>20</i>
1	TO CONDUCT WHEEL ALIGNMENT	200.00	<i>100</i>
Sub Total		4,750.00	0.00

SUB-TOTAL	20,563.46	0.00
GST - 7 %	1,439.44	0.00
TOTAL	22,002.90	0.00

ABWIN SERVICE PTE LTD

Prepared By

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

2-4659-78
252
P-3494-83
S.N- 660
L-2310
6464-87