

REG. BY: Theran

DATE: N/A

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % ✓ 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD8533k ✓

Yr Regn: 12/5/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / PR / Prime Mover /

Truck / Trailer or

Make: Hyundai

c.c 1685

Colour: Yellow

NC: Insured / Std / HI / NA

Sp. Reading: 700299

T/Radio: Insured / Std / HI / NA

Eng/No: _____

C/No: HMHLB4UM6U089069

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size: F: 206/60R16

R: 206/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. 5

mm

R/Bal. 5

mm

L/Bal. 5

mm

L/Bal. 5

mm

D.O.A. 22/12/21

D.O.I. 23/12/21

1630

Survey held at

CDGE

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

NO GIA given

Date/Time. File Pass to?

☐

: Procl. Report

ij

☐

: Final Report

Date/Time. File Return to?

7

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: _____

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel end

Survey Fee: _____

Transportation: _____

____ \$ + RS. ____ \$

Prints

Others

Total

Report Form 1:

Form 144 / 145 / 146

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD8533K

Date: 23/12/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT DOOR MIRROR LH			\$670.00
1	FRT DOOR MIRROR HOLDER LH			\$62.40
1	FRT DOOR LH			\$2,256.40
1	FRT DOOR GLASS LH			\$316.30
1	FRT DOOR OUTER HANDLE LH			\$132.30
1	FRT DOOR OUTER MOULDING LH			\$153.10
1	FRT FENDER LH			\$663.00
	SUB TOTAL			\$4,253.50
	LESS 20%			\$850.70
	DISCOUNTED TOTAL			\$3,402.80
	FRT DOOR COMFORT LOGO LH			\$75.00
				\$75.00
	Labour Charge			
	PANEL BEATING			\$900.00
	SPRAY PAINTING CHARGE			\$650.00
	TRANSFER OF FRT DOOR			\$120.00
	TUFF KOTE			\$60.00
	CHECK ALL LIGHTING			\$60.00
	TOTAL LABOUR			\$1,790.00
	ESTIMATE TOTAL			\$5,267.80

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan @ LKH auto - low
 822 35767
 L/S after repair photo
 3 days up
 23/12/21 1630

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 23.12.2021 13:07

Page : 1

nam: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4155170


JC NO:305498866

TOMER AS CITYCAB PTE LTD TOMER NO 7010070 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O) (P) COUNT CARD NO.	REGN NO SHD8533K	MILEAGE
	MAKE HYUNDAI	FUEL E. 12. F
	MODEL I-40	DATE/TIME IN 22.12.2021 17:25
	YR OF MANU 12.05.2016	TARGET DATE
	CHASSIS CODE KMHLB41UMGU089069	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 22.12.2021
NATURE: 3P 22.12.2021

/NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

acknowledgement Slip

Exit Pass

No.: SHD8533K YY

Vehicle No.: SHD8533K

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard