

File No: Thavan

File No: Ntuc

NS/INC22000459/Vqc

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Clnms No

MT/1155733-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est Repairs:

2

days

Res: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC8177k

Vr Regn:

9/6 116

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai 140

cc 1685

Colour:

blue

AC: Insured / Std / HI / NA

Sp. Reading

692763

T/Radio: Insured / Std / HI / NA

Eng/No:

C/No:

KMH134um6409/325

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

206/60R16

R:

206/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/12/11

D.O.A.

23/12/11 1700

Survey held at

CDGE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/tp or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No GIA given

Thevan finalised LS \$2550, 2 days (Red \$3276, 56%)

Date/Time, File Pass to?

☐

: Procl. Report

26/01 Typist

☐

: Final Report

Date/Time, File Return to?

2

Days Of Repair: 2

Resurvey No. of Trip: 3

Add For:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invg (\$

☐

: Visual Insp (\$

Survey Fee:

Transportation:

\$ + R.S. \$

Phone

Driver

Total

Request Forbid:

TP

2550

2550

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8177K ✓

Date: 23/12/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$553.00
1	REAR BUMPER CLIPS			\$22.00
1	REAR BUMPER LOWER COVER			\$228.00
1	REAR BUMPER REFLECTOR LAMP LH			\$32.00
1	EXHAUST SILENCER LH			\$967.70
1	EXHAUST PIPE CENTRE			\$730.10
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER REINFORCEMENT BRACKET LH			\$160.60
1	TAIL LAMP LH			\$697.80
	SUB TOTAL			\$3,819.60
	LESS 20%			\$763.92
	DISCOUNTED TOTAL			\$3,055.68
	REAR FENDER ADVERTISEMENT LOGO			\$100.00
	REAR BUMPER RUBBER MAT			\$50.00
	REAR BUMPER ADVERTISEMENT LOGO			\$50.00
				\$200.00
	Labour Charge			
	TUFF KOTE			\$60.00
	CHL ALL LIGHTING			\$60.00
	REMOVE AND REFIX EXHAUST PIPE			\$150.00
	PANEL BEATING			\$900.00
	SPRAY PAINTING CHARGE			\$300.00
	TOTAL LABOUR			\$1,410.00
	ESTIMATE TOTAL			\$4,665.68

LHK Auto Consultants
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Thuan@LHKauto.com

82235769

LIC after repair photo

23/12/21 1700

2 days swp ✓

Date/Time: 23.12.2021 14:30

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4155186

JC NO305498869


CUSTOMER	REG NO	MILEAGE
COMFORT TRANSPORTATION PTE LTD	SHC8177K	
VMS 7010045	MAKE	FUEL
CUSTOMER NO. 383 SIN MING DRIVE	HYUNDAI	E.....1/2.....F
ADDRESS Singapore SINGAPORE 575717	MODEL	DATE/TIME IN
L (R) 65508755 (O)	I-40	23.12.2021 11:35
(P)	YR OF MATH	TARGET DATE
	09.06.2016	
SCOUT CARD NO.	CHASSIS CODE	COMPLETION DATE/TIME:
	KMHLB41UMGU091325	

JOB DESCRIPTION

Accident Date: 23.12.2021

NATURE: 3P 23.12.2021

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

ie:

Vo.:

cle No.:

SHC8177K

YY

Vehicle No.:

SHC8177K

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard