

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AIG ASIA PACIFIC	INSURANCE PTE LTD	Ref:	CS3/AIG21001874/Apq2-1	
	78 SHENTON WAY AIG BUILDING SINGAPORE 0791		Date:	12/01/2022	
	ATTN:JEREMY		Code:	AIG	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 7097C	Veh. Inspected	SKQ 6377D	
	Policy No.	1900245464	Coverage (\$)	0.00	
	Claim No.	3803188575SG	Excess (\$)	0.00	
	Assign From		Assign Date	08/02/2021	
2. Vehicle Particulars & Condition					
	Make & Model	RENAULT CAPTUR	c.c	1461	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	VF12REL1E51557079	Colour	GREY	
	Odometer	165221 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/50 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	215/50 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	215/50 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	215/50 R17	BRIDGESTONE	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	5. General Information				
	Accident Date	05/02/2021	Inspection Date	09/02/2021	
	Survey held at	TRIDENTE AUTOMOBILI PL			
	30 LENG KEE ROAD SINGAPORE 159100				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 21 Working Days				