



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2205163

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 19/08/2022
Reference CC3/CTI22000460/Vea3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SH 9601P
Insured Veh. GBK 6047U
Claim No. SNM22D200334/C02
Policy No. DMCVSNW001165772100
Accident Date 29/12/2021
Inspection Date 31/12/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI22000460/Vea3q2	
			Date: 19/08/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBK 6047U	Veh. Inspected	SH 9601P	
Policy No.	DMCVSNW001165772100	Coverage (\$)	0.00	
Claim No.	SNM22D200334/C02	Excess (\$)	0.00	
Assign From		Assign Date	31/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHLB41UMHU098598	Colour	BLUE	
Odometer	511231 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	206/60 R16	WEST LAKE	5 mm	
L/H Front Tyre	206/60 R16	WEST LAKE	5 mm	
R/H Rear Tyre	206/60 R16	WEST LAKE	5 mm	
L/H Rear Tyre	206/60 R16	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/12/2021	Inspection Date	31/12/2021	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9601P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TO REPAIR SEE LABOUR	553.00	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	228.00	-
1	REAR BUMPER SPONGE	NOT NECESSARY	119.50	-
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	428.40	-
2	REAR BUMPER REINFORCEMENT BRACKET LH/RH @ \$80.30	NOT NECESSARY	160.60	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
	LESS 20% DISCOUNT		-302.30	-4.40
			1,209.20	17.60
<u>SPECIAL NETT ITEMS</u>				
2	REAR FENDER ADV .STICKER RH/LH @\$100.00 (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER ADV STICKER (SN)	NECESSARY	50.00	50.00
1	REVERSE SENSORS (SN)	CUT	135.70	135.70
1	REAR BUMPER MAT (SN)	SERVICEABLE	50.00	-
			435.70	385.70
<u>LABOUR</u>				
	PANEL BEATING.INCLUDING OF THE REPAIR OF REAR BUMPER .		300.00	280.00
	SPRAY PAINTING CHARGE.		300.00	250.00
	R/I REVERSE SENSORS.		120.00	30.00
	TOWING FEE-CHIT ATTACHED.		60.00	60.00
			780.00	620.00
GRAND TOTAL			2,424.90	1,023.30

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			800.00
---	--	--	---------------

Report Ref No. CC3/CTI22000460/Vea3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 9601P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SH 9601P

RE-INSPECTION

