

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000463/BVF3N2**Date:** 23/02/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00045792101

Claimant Vehicle No : SKL4069H**Insured Vehicle No :** EN3822S

Date of Loss: 07/01/2022

Nature of Claim: TP

Claim No: SNM22D200185/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKL4069H**Make & Model: MERCEDES-BENZ CLA 200, 1.3 SB PROGRESSIVE
(A)

Engine No: 27091030245668

Reg. Date: 05/11/2013 (Man. Year: 2013)

Chassis No: WDD1173432N033748

Colour: White

Odometer: 163009 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/35R19

Rear Tyre Size: 235/35R19

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,505.20	2,526.10	7,979.10	75.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	880.00	2,420.00	73.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,805.20	3,406.10	10,399.10	75.33
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	13,805.20	2,700.00	11,105.20	80.44
+ GST 7.00/7.00% (S\$)	966.36	189.00	777.36	80.44
Nett Amount (S\$)	14,771.56	2,889.00	11,882.56	80.44

INSPECTION

Date of Assignment: 13/01/2022

Date Inspected: 13/01/2022 Inspected At:

Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: Lim Teow Guan**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Feb 2022)

Parts: 143 MERCEDES-BENZ CLA 200 1.3 SB PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL4069H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FRONT FENDER	Dented	783.00 FL	*783.00 FL
2	1		*RH FRONT FENDER SPLASH SHIELD	Not Damaged	231.00 FL	*- FL
3	1		*RH FRONT DOOR	Dented	1,468.00 FL	*1,468.00 FL
4	1		*RH FRONT DOOR WEATHERSTRIP	Necessary	278.00 FL	*278.00 FL
5	1		*RH FRONT DOOR UPPER HINGE	Not Damaged	216.00 FL	*- FL
6	1		*RH FRONT DOOR LOWER HINGE	Not Damaged	216.00 FL	*- FL
7	1		*RH FRONT DOOR INNER TRIM BOARD	Not Damaged	783.00 FL	*- FL
8	1		*RH FRONT DOOR INNER ABSORBER	Not Damaged	68.00 FL	*- FL
9	1		*RH SIDE MIRROR ASSY	Not Damaged	695.00 FL	*- FL
10	1		*RH SIDE MIRROR COVER	Not Damaged	316.00 FL	*- FL
11	1		*RH SIDE ROCKER PANEL GARNISH	Not Damaged	542.00 FL	*- FL
12	1		*RH SIDE ROCKER PANEL GARNISH SPOILER	Not Damaged	218.00 FL	*- FL
13	1		*RH FRONT LOWER ARM	Not Damaged	583.00 FL	*- FL
14	1		*RH FRONT KNUCKLE ARM	Not Damaged	988.00 FL	*- FL
15	1		*RH FRONT WHEEL BEARING	Not Damaged	452.00 FL	*- FL
16	1		*RH FRONT SHOCK ABSORBER	Not Damaged	742.00 FL	*- FL
17	1		*RH FRONT CONTROL ARM	Not Damaged	582.00 FL	*- FL
18	1		*RH FRONT TIE EOD END	Not Damaged	117.00 FL	*- FL
19	1		*RH FRONT DOOR ART STICKER	Necessary	220.00 FS	*220.00 FS
20	1		*BRAKE FLUID	Not Necessary	75.00 FS	*- FS
21	1		*RH FRONT SPORT WHEEL	Not Necessary	1,200.00 FS	*- FS
22	1		*RH FRONT TYRE	Not Necessary	380.00 FS	*- FS
23	1		*SET RH FRONT FENDER SPLASH SHIELD	Not Necessary	70.00 FS	*- FS
24	1		*SET RH SIDE ROCKER PANEL GARNISH	Not Necessary	70.00 FS	*- FS
25	1		*SET FRONT BUMPER CLIPS	Not Necessary	70.00 FS	*- FS
26	1		*SET RH FRONT DOOR INNER TRIM BOARD CLIPS	Necessary	70.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,433.00	2,779.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	927.80	252.90
Total Parts (\$\$)	10,505.20	2,526.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE,CHECK,REPLACE AND REINSTALL DAMAGES BODYPARTS,TO PANEL BEATING,CUT/WELD AND RE-ALIGN ALL AFFECTED PANELS	New	1,000.00	400.00
2	SPRAY PAINTING ON AFFECTED PANELS	New	1,000.00	400.00
3	CHECK WIRING AND LIGHTING SYSTEM	New	80.00	0.00
4	APPLY RUST COATING CHEMICAL ON AFFECTED PANELS	New	60.00	0.00
5	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS TO ASSIST REPAIR	New	320.00	0.00
6	TEST DRIVE AND ADJUST WHEEL ALIGNMENT SYSTEM	New	100.00	0.00
7	REMOVE AND REPLACE RH FRONT DOOR INNER MECHANISM TO NEW DOOR	New	120.00	80.00
8	BALANCE AND REPLACE RH FRONT RIM AND TYRE	New	60.00	0.00
9	REFOCUS AND ADJUST HEADLAMPS ASSY	New	60.00	0.00
10	REMOVE AND REINSTALL FRONT BUMPER DISTANCE SENSORS TO ASSIST REPAIR	New	120.00	0.00
11	RESET AND DIAGNOSE CONTROL UNIT AND FAULT CODE AFTER REPAIR	New	380.00	0.00
Gross Labour Cost (\$)			3,300.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >