



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22000469/Uqy3e2	
			Date: 20/02/2023	
			Code: UOI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBJ 5414E	Veh. Inspected	FBF 1377B
	Policy No.		Coverage (\$)	0.00
	Claim No.	M11D14482201	Excess (\$)	0.00
	Assign From	JOSEPHINE WONG	Assign Date	13/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	YAMAHA FZ 16	c.c	153
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	ME121C051B2026437	Colour	GREY
	Odometer	35682 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	100/80-17	MICHELIN	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70-17	MICHELIN	6 mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	08/01/2022	Inspection Date	13/01/2022
	Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	