



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

UNITED OVERSEAS INSURANCE LTD
3 ANSON ROAD
#28-01 SPRINGLEAF TOWER
SINGAPORE 079909

NO. : 41256

- Rev. 1

Supplementary 1 To QTN: 39855

DATE : 01/08/2022

CLAIM NO. : 11848

POLICY NO. : MC/00577015/02

FROM : RAYMOND

VEHICLE NO. : FBF1377B

MAKE/MODEL : /

S/N	Description	Action	Qty	Unit Price	Amount
1	CLAMP EXHAUST P/N: 74292	Replace	1.00	\$84.00	84.00
2	EMBLEM SET SQUARE C SUS/TI YOSHIMURA P/N: 74141	Replace	1.00	\$126.00	126.00
3	RE-COVER MUFFLER P/N: 17881	Replace	1.00	\$480.00	480.00
4	SWITCH NEUTRAL P/N: 74298	Replace	1.00	\$14.00	14.00

SUB TOTAL

\$704.00

GST @ 7 %

\$49.28

GRAND TOTAL (SGD)

\$753.28

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*41256 *

bizSAFE₃



Address: No.6, Defu Lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) + 65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	 RAYMOND				

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*39855 *

bizSAFE₃

