

**CHEONG CHEONG MOTOR SERVICE PTE LTD**

BLK 5032 ANG MO KIO IND. PARK 2 #01-293 SINGAPORE 569535

TEL : 6481 4152 FAX : 6481 4157

e-mail : c2msvc@singnet.com.sg

Our Ref : 0569/01/2022

Page : 1

Date : 12/01/2022

M/S

ALLIANZ INSURANCE SINGAPORE PL  
MARINA VIEW #14-01  
ASIA SQUARE TOWER 2  
SINGAPORE 018961

ACCIDENT REPAIR ON : SJS 9559 C - TOYOTA ALTIS 1.6  
POLICY NO :  
DATE OF ACCIDENT : 08/01/2022

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED :-

**REPLACEMENT OF PARTS**

- 1 FRONT BONNET
- 2 FRONT BUMPER
- 3 FRONT GRILLE
- 4 FRONT NUMBER PLATE
- 5 FRONT NUMBER PLAT FRAME

489.60  
486.10

|          | S\$ | S\$   |
|----------|-----|-------|
| 1,140.40 | ✓   |       |
| 564.60   | ✓   |       |
| 559.50   | ✓   |       |
| S/NETT   |     | 20.00 |
| S/NETT   |     | 20.00 |
| 2,264.50 |     |       |
| 566.12   |     |       |
| 1,698.38 |     |       |
| 1,738.38 |     |       |

LESS : 25%

**ABOUT CHARGES :**

- 6 KNOCKING PUSH OUT FRONT ACCIDENT PARTS  
STRIP / REFIT ABOVE ACCESSORIES
- 7 SPRAY PAINT & SPRAY ANTI-TUFF-KOTE ON FRONT  
ACCIDENT AFFECTED AREAS

320  
400.00  
480.00

2,618.38



Not Notarised  
L18501  
Heavy After Rain

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3 days