

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000476/KVF3N2**Date:** 11/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00079982105

Claimant Vehicle No : SKV59K **Insured Vehicle No :** SKS5989J

Date of Loss: 09/01/2022 Nature of Claim: TP Claim No: SNM22D200288/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKV59K**

Make & Model: MERCEDES-BENZ E200 AVG, 2.0 (R18 LED) (A) Engine No: 27492031659806

Reg. Date: 19/11/2018 (Man. Year: 2018) Chassis No: WDD2130422A550583

Colour: Metallic Pearl Red Odometer: 82934 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45R18 Rear Tyre Size: 245/45R18

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,202.60	4,327.80	874.80	16.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	820.00	680.00	45.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,702.60	5,147.80	1,554.80	23.20
Approved Total (Overridden) (\$\$)		4,100.00		
(\$\$)	6,702.60	4,100.00	2,602.60	38.83
+ GST 7.00/7.00% (\$\$)	469.18	287.00	182.18	38.83
Nett Amount (\$\$)	7,171.78	4,387.00	2,784.78	38.83

INSPECTION

Date of Assignment: 13/01/2022

Date Inspected: 22/02/2022 Inspected At: 160 SIN MING DRIVE #03-18/19
SIN MING AUTOCITY
SINGAPORE 575722
REPAIRER: EM SOLUTION PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 11 Mar 2022)

Parts: 143 MERCEDES-BENZ E200 AVG 2.0 (R18 LED) (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKV59K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Buckled/Dented	1,422.00 FL	*1,422.00 FL
2	1		*FRT BUMPER SIDE HOLDER RH	Serviceable	32.00 FL	*- FL
3	1		*FRT BUMPER GARNISH RH	Serviceable	90.00 FL	*- FL
4	1		*PDC PARKING SENSOR (2 Pcs)	Shorted (1 Pc only)	390.00 FL	*195.00 FL
5	1		*HEADLAMP RH	Mtg Cracked	3,780.00 FL	*3,125.00 FL
6	1		*SET FRT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,774.00	4,802.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	571.40	474.20
Total Parts (\$\$)	5,202.60	4,327.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS,CHECK LIGHTINGS	New	100.00	20.00
2	TO REMOVE,REPAIR & REPLACE DAMAGED BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT	New	400.00	250.00
3	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	500.00	400.00
4	RUST PROOFING ON AFFECTED PORTIONS	New	100.00	0.00
5	NANO COATING	New	400.00	150.00
Gross Labour Cost (\$)			1,500.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >