

⏪

<

1

of 2 ?

>

⏩

↺

↻

100%

▼

💾

✓

🖨

Find | Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD #16-00

SPRINGLEAF TOWERSINGAPORE 079909

Ref: CS/CTI22000476/Kvf3

Date: 13/01/2022

Code: CTI

1.

Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKS 5989J	Veh. Inspected	SKV 59K
Policy No.	DMPCSNW00079982105	Coverage (\$)	0.00
Claim No.	SNM22D200288/C02/TOHHS	Excess (\$)	0.00
Assign From	MERIMEN (ALFRED TOH)	Assign Date	13/01/2022

2.

Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3.

Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4.

Description of Damages

--

5.

General Information

Accident Date	09/01/2022	Inspection Date	22/02/2022
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		

5a.

Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

https://views.init.com.sg/report/reportserver?Report=LKKInspection&From=344123&rs:Command=Render&rc:Parameters=false&rc:Zoom=Page ...

1/1