



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Ref: CS3/ASM22000477/y3

Date: 13/01/2022

Code: ASM

#### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 3536R	Veh. Inspected	SMC 8939U
Policy No.		Coverage (\$)	0.00
Claim No.	S1M03NE0	Excess (\$)	0.00
Assign From	LYNN KHONG (SMART CLAIMS)	Assign Date	13/01/2022

#### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

#### 4. Description of Damages

--	--

#### 5. General Information

Accident Date	29/11/2021	Inspection Date	
Survey held at	BLK 160 SIN MING AUTOCITY #02-16 S(575722)		
Repairer	CMK MOTOR SERVICE REPAIR		

#### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.