

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair EstimateVehicle number: **SBN 8529S**

Make & Model: Mercedes Banz GLA180

Chassis number: WDC1569422J504733

✓
DOA 10/1/2022

DN 14/1/2022

2018

No.	Description of spare parts	Qty	List price	Amount
1	Tailgate	1	2025.00	\$ 2,319.00
2	Tailgate windscreen glass	1		\$ 988.00
3	Tailgate windscreen glass RH side garnish	1		\$ 76.00
4	Tailgate windscreen glass LH side garnish	1		\$ 76.00
5	Tailgate windscreen glass upper centre garnish	1	108.20	\$ 158.00
6	Tailgate wiper motor	1	434.40	\$ 543.00
7	Tailgate wiper arm	1	100.00	\$ 127.00
8	Tailgate wiper arm cover	1	13.00	\$ 13.00
9	Tailgate wiper blade	1	30.00	\$ 48.00
10	Tailgate "GLA180" emblem	1		\$ 86.00
11	Tailgate centre emblem	1		\$ 78.00
12	Tailgate RH lamp assy	1	598.00	\$ 719.00
13	Tailgate LH lamp assy	1	598.00	\$ 719.00
14	Tailgate chrome moulding	1		\$ 231.00
15	Tailgate RH number plate lamp assy	1		\$ 63.00
16	Tailgate LH number plate lamp assy	1		\$ 63.00
17	Tailgate reverse camera	1		\$ 845.00
18	Tailgate lock	1	318.00	\$ 401.00
19	Tailgate lock catch	1		\$ 55.00
20	Tailgate inner trim board	1		\$ 387.00
21	Tailgate RH damper	1		\$ 203.00
22	Tailgate LH damper	1		\$ 203.00
23	Tailgate RH hinge	1		\$ 192.00
24	Tailgate LH hinge	1		\$ 192.00
25	Tailgate weatherstrip	1		\$ 195.00
26	Rear bumper	1	1250.00	\$ 1,519.00
27	Rear bumper upper chrome garnish	1	260.00	\$ 342.00
28	Rear bumper (centre)	1	769.00	\$ 944.00
29	Rear bumper lower garnish	1	525.00	\$ 759.00
30	Rear bumper RH side reverse sensor	1	170.00	\$ 225.00
31	Rear bumper RH centre reverse sensor	1	170.00	\$ 225.00
32	Rear bumper LH centre reverse sensor	1	170.00	\$ 225.00

DOA ✓

BR ✓

NECV

BT ✓

NECV

BR

BT ✓

NDX

NDX

JMW

NDX

NDX

NDX

BR ✓

BR ✓

SCV ✓

33	Rear bumper LH side reverse sensor	1	170.00	\$	225.00
34	Rear bumper reverse sensor O-seal	4		\$	✓ 39.00
35	Rear bumper reverse sensor wire harness	1		\$	322.00
36	Rear bumper RH exhaust chrome finisher	1	385.00	\$	415.00
37	Rear bumper LH exhaust chrome finisher	1	385.00	\$	415.00
38	Rear bumper towing cover	1	55.00	\$	67.00
39	Rear bumper RH lower bracket	1		\$	✓ 82.00
40	Rear bumper LH lower bracket	1		\$	✓ 82.00
41	Rear bumper RH side lower bracket	1		\$	18.00
42	Rear bumper LH side lower bracket	1		\$	18.00
43	Rear bumper RH side bracket	1		\$	152.00
44	Rear bumper LH side bracket	1		\$	152.00
45	Rear bumper reinforcement	1	595.00	\$	787.00
46	RH taillamp assy	1	925.00	\$	936.00
47	LH taillamp assy	1	925.00	\$	936.00
48	Rear RH fender	1	1650.00	\$	1,758.00
49	Rear RH fender arch moulding	1	280.00	\$	358.00
50	Rear RH fender inner trim board	1		\$	303.00
51	Rear RH fender inner upper trim	1		\$	164.00
52	Rear RH fender LH	1	1650.00	\$	1,758.00
53	Rear RH fender arch moulding LH	1	280.00	\$	358.00
54	Rear RH fender inner trim board LH	1		\$	✓ 303.00
55	Rear RH fender inner upper trim LH	1	96.00	\$	164.00
56	End panel	1	1015.00	\$	1,687.00
57	End panel inner garnish	1		\$	✓ 231.00
58	Rear upper tray cover	1		\$	486.00
59	Rear compartment panel	1		\$	953.00
60	Rear compartment panel insulator	1		\$	158.00
61	Rear compartment panel top cover	1		\$	389.00
62	Exhaust silencer	1		\$	1,648.00
63	Exhaust silencer heat shield	1	126.00	\$	255.00
64	Exhaust silencer rubber mouldings mounting	2	152.00	\$	✓ 152.00
65	Driver seat belt	1	355.00	\$	673.00
66	Driver seat belt buckle	1		\$	176.00
67	Front passenger seat belt	1	355.00	\$	673.00
68	Front passenger seat belt buckle	1		\$	176.00
69	Rear RH passenger seat belt	1	355.00	\$	505.00
70	Rear RH passenger seat belt buckle	1		\$	158.00
71	Rear centre passenger seat belt	1		\$	505.00
72	Rear centre passenger seat belt buckle	1		\$	158.00
73	Rear LH passenger seat belt	1	355.00	\$	505.00
74	Rear LH passenger seat belt buckle	1		\$	158.00
75	Airbag control unit	1	760.00	\$	907.00
76	RH rear sport rim nn	1	622.00	\$	876.00
77	RH rear lower arm	1		\$	421.00
78	RH rear knuckle arm	1		\$	988.00
79	RH rear shock absorber nn	1	488.00	\$	627.00
80	RH rear wheel bearing nn	1	320.00	\$	387.00
81	RH rear trailing arm	1		\$	356.00
82	RH rear control arm	1		\$	465.00

SCV
 NECV
 NDX
 DDV
 CUTV
 BRV
 ?
 NSX
 BTV
 BRV
 DDV
 CUTV
 RPT
 DDV
 CUTV
 BRV
 DDV
 BRV
 NDX
 NDX
 DLV
 NECV
 Activated
 NDX
 Activated
 NDX
 Activated
 NDX
 Activated
 NDX
 Activated
 NDX
 Activated
 CUTV
 NDX
 ? BTV
 Umv
 NDX

83	RH rear upper arm	1	\$ 478.00
84	Rear undercarriage crossmember	1	\$ 1,463.00
85	Front bumper	1	\$ 1,559.00
86	Front bumper emblem	1	\$ 71.00
87	Front bumper emblem lock clips	2	\$ 12.00
88	Front bumper lower garnish	1	\$ 415.00
89	Front bumper RH side distance sensor	1	\$ 225.00
90	Front bumper distance sensor O-seal	4	\$ 41.00
91	Front bumper centre garnish (sliver)	1	\$ 624.00
92	Front bumper lower cover	1	\$ 451.00
93	RH front fender arch moulding	1	\$ 378.00
94	RH headlamp assy	1	\$ 2,409.00
95	RH front sport rim	1	\$ 876.00
96	RH front shock absorber	1	\$ 693.00
97	RH front lower arm	1	\$ 583.00
98	RH front knuckle arm	1	\$ 988.00
99	RH front wheel bearing	1	\$ 452.00
100	RH front sway bar linkage	1	\$ 102.00
101	RH front tie rod end	1	\$ 117.00
102	RH front control arm	1	\$ 582.00
103	Steering rack and pinion	1	\$ 2,873.00
104	Engine RH mounting	1	\$ 464.00
105	Engine centre mounting	1	\$ 482.00
106	Gearbox mounting	1	\$ 472.00
		Total	\$ 54,374.00
		Less 10%	\$ 5,437.40
		Total	\$ 48,936.60

?NDX

NDX

No.	Special Nett Items		Amount
1	Tailgate windscreen glass sealant	1	30.00 \$ -70.00
2	Tailgate windscreen glass inner seal	1	20.00 \$ 50.00
3	Tailgate "C&C" emblem	1	50.00 \$ -85.00
4	Tailgate inner trim board clips	1set	30.00 \$ -70.00
5	Tailgate windscreen glass RH side garnish clips	1set	10.00 \$ -30.00
6	Tailgate windscreen glass LH side garnish clips	1set	10.00 \$ -30.00
7	Tailgate windscreen glass upper centre garnish clips	1set	30.00 \$ -50.00
8	Rear bumper clips	1set	30.00 \$ -70.00
9	Rear number plate	1	30.00 \$ -70.00
10	Rear RH fender joint sealant	1	30.00 \$ -70.00
11	Rear RH fender arch moulding clips	1set	30.00 \$ -55.00
12	Rear RH fender inner trim board clips	1set	20.00 \$ -70.00
13	Rear RH fender inner upper trim clips	1set	20.00 \$ -40.00
14	Rear LH fender joint sealant	1	30.00 \$ -70.00
15	Rear LH fender arch moulding clips	1set	30.00 \$ -55.00
16	Rear LH fender inner trim board clips	1set	30.00 \$ -70.00
17	Rear LH fender inner upper trim clips	1set	20.00 \$ -40.00

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

NECV

18	End panel inner garnish clips	1set	30.00	\$ 50.00
19	End panel joint sealant	1	30.00	\$ 60.00
20	Rear compartment panel joint sealant	1	30.00	\$ 70.00
21	RH rear tyre	1		\$ -380.00
22	RH front tyre	1		\$ -380.00

NECV
? NECV
NDX

	Labour and painting			Amount
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	1400.00	\$	2,200.00
2	Spray painting on affected areas and panels	1000.00	\$	1,000.00
3	Check wiring and lighting system	50.00	\$	120.00
4	Apply rust coating chemical on affected areas and panels		\$	100.00
5	Replace tailgate windscreen glass and sealants	120.00	\$	220.00
6	Remove and replace tailgate inner mechanism to new tailgate	80.00	\$	180.00
7	Remove and replace tailgate reverse camera to assist repair		\$	100.00
8	Remove and replace rear bumper reverse sensors and wire harness to assist repair	60.00	\$	150.00
9	Remove and replace rear inner trim and boards to assist repair	160.00	\$	250.00
10	Remove and replace exhaust silencer, gasket and chrome finishers to assist repair	80.00	\$	220.00
11	Remove and reinstall fuel tank, pipes, hoses and sensor to assist repair		\$	200.00
12	Remove and reinstall roof lining, carpet and seats to assist repair		\$	480.00
13	Remove and replace front and rear seat belts and buckles to assist repair	300.00	\$	550.00
14	Reset and diagnose control unit and fault code after repair	120.00	\$	450.00

NNX

NNX

NNX

NNX

