

1 of 2 ?

100%

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

64 CECIL STREET

#05-02 IOB BUILDING SINGAPORE 049711

Ref: ~~CS3/GRB21012831/R1vf3-1~~

Date: 11/01/2022

Code: GRB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SNC 2169C	Veh. Inspected	SKR 8909B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	SNC 2169C CARINE KEK	Assign Date	20/12/2021

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	17/12/2021	Inspection Date	20/12/2021
Survey held at	KOI MOTOR WORKS BLK 176 SIN MING DRIVE #04-12 SIN MING AUTOCARE SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

https://views.init.com.sg/report/reportserver?Report=LKKInspection&From=343097&rs:Command=Render&rc:Parameters=false&rc:Zoom=Page ...

1/1