

CS/CTA 20000482 | Kv3

KV

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model : TOYOTA VIOS 1.5 (A) 2008

Engine/Chassis No :

Date of accident : 10/01/2022

Damaged area : Rear

Date : 19/01/2022

Claim Type : TP

VRN : SGY 4978M

NOT Withair
 11pm @ 3000hr
 Picking After Picking
 3 days

List items

S/N	Parts description	QTY	AMOUNT
1	Rear Bumper Assy <i>R</i>	1 pc	495.7
2	Rear Bumper Clips <i>nu</i>	1 set	80 <i>50</i>
3	Rear Bumper Reflectors <i>ols my am</i>	2 pcs	190
4	Rear Bumper Side Retainers <i>ols p</i>	2 pcs	205.6
5	Rear End panel <i>590</i> <i>R</i>	1 pc	698.5
6	Rear End panel garnish <i>158-60</i> <i>mt. n</i>	1 pc	225.5
7	Rear ENF panel garnish clips <i>nu</i>	1 set	50
8	Spare Tyre compartment panel <i>R</i>	1 pc	637.7
9	Tail lamps <i>C 283-75</i> <i>ols am</i>	2 pcs	684.8
10	Tail lamps gasket <i>ols nu</i>	2 pcs	70.2
11	Tail lamp panels <i>R</i>	2 pcs	233
12	Rear Fenders <i>R</i>	2 pcs	1,670.6
13	Rear fender inner garnish <i>Pu</i>	2 pcs	495.5
14	Rear fender inner garnish clips <i>nu</i>	2 set	100
15	Rear Boot Assy <i>681-20</i> <i>R</i>	1 pc	720.6
16	Rear Boot hinges <i>R</i>	2 pcs	130.9
17	Rear Boot rubber <i>nd/ha</i>	1 pc	195.5
18	Rear Boot lock <i>nd</i>	1 pc	109.5
19	Rear Boot latch <i>R</i>	1 pc	13.55
20	Rear Boot logo <i>nu</i>	1 pc	53.9
21	Rear Boot outer handle <i>su</i>	1 pc	181.7
22	Rear Emblem "VIOS" <i>nu</i>	1 pc	51.9
23	Rear Emblem "E" <i>nu</i>	1 pc	40.2
Total :			7,334.85
Less 25%			5,501.14

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Special nett items

No.	Parts description	QTY	AMOUNT
1	Reverse Sensors <i>shan</i>	1 set	280
2	Rear Bumper lower skirt <i>NIP</i>	1 pc	800
3	Rear Boot top spoiler <i>NIP</i>	1 pc	800
4	Rear number plate <i>su</i>	1 pc	80
5	Rear Emblem "SPORT" <i>NIP</i>	1 pc	50
6	Panel sealant <i>nu</i>		100
Total :			2,110

Labour

No.	Description	Amount
1	Panel Beating	1,000
5	Spray Painting	1,000
7	Anti Rust	100
Total labour :		2,100
Grand Total :		9,711.14

600h
 700h
 60h