

ASS. REC. BY: Tauph

REF:

CS/ASM 22 000 484/Tig 3.

ASSIGNMENT

Co E 2030 Aug.
2011 Jan.

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. S2M03QLV

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 460K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJZ9196D Yr Regn: 2011 Jan.

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Scirocco c.c. 1390.Colour: Green A/C: Insured / Std / NI / NASp. Reading: 144 036 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW ZZZ 13Z BV 9 63 24Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: 235/40R18R: 17

(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 14/1/22 @ 20pmSurvey held at TSL Auto.

Des. of Damages (Frt) Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

09/05/22 @ 1.55pm revised to Yvonne Ang via Smart Claims.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

Photos _____

Others _____

Report Format: _____

Lump Sum / I.B.J. (\$ _____)

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJZ9196D Volkswagen Scirocco

No	Qty	Parts Description	Estimated Parts Price
1	1	Front bumper reinforcement	\$ 374.60X
2	1	Front bumper absorber foam	\$ 163.40X
3	2	Front bumper retainers	\$ 138.20 X
4	2	Front bumper brackets	\$ LHX 125.60 RMa-
5	1	Front bumper lower grille	\$ 282.40 ac-
6	1	Front bumper tow cover	\$ 88.80 X
7	1	Front left day lamp	\$ 350.50 X
8	1	Front right day lamp	\$ 350.50 ac-
9	1	Front left day lamp garnish	\$ 179.30 X
10	1	Front right day lamp garnish	\$ 179.30 ac-
11	1	Front grille assy	\$ 446.80 ac-
12	1	Front bonnet emblem	\$ 128.10 ac-
13	1	Front bonnet lock mechanism	\$ 225.60 X
14	1	Front left HID headlamp support panel	\$ 371.50X
15	1	Front right HID headlamp support panel	\$ 371.50 X
16	1	Front right fender	\$ 819.30 RY
17	1	Front right fender inner cowl	\$ 129.30 in-
18	1	Front left spray nozzle	\$ 191.30 X
19	1	Front right spray nozzle	\$ 191.30 X
20	1	Front left spray nozzle cover	\$ 88.10 X
21	1	Front right spray nozzle cover	\$ 88.10 X
22	1	Front radiator assy	\$ 1,420.80 X
23	1	Front radiator cooling fan cowl	\$ 170.90 X
24	1	Front radiator cooling fan blade with motor assy	\$ 783.20 X
25	1	Front radiator top hose	\$ 91.20X
26	1	Front radiator bottom hose	\$ 91.20X
27	1	Front air-con cooling fan blade with motor assy	\$ 503.10X
28	1	Front air-con cooling fan cowl	\$ 160.90X
29	1	Front air-con condenser	\$ 1,183.90 X
30	1	Front air-con discharge pipe	\$ 280.10X
31	1	Front air-con suction pipe	\$ 280.10X
32	1	Front air intake duct	\$ 117.60X
33	1	Front turbo-intercooler assy	\$ 898.20 X
34	1	Front support panel complete assy	\$ 739.50X
35	1	Front support panel top garnish	\$ 179.10X
			\$ 12,183.30
less 10%			\$ 1,218.33
			<u>\$ 10,964.97</u>

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJZ9196D Volkswagen Scirocco

No	Qty	Parts Description	Estimated Parts Price
----	-----	-------------------	--------------------------

Special Nett Items

1	1	Front sport bumper assy	\$ 2,500.00 <i>aw 1000</i>
2	12	Front sport bumper clips	\$ 60.00 <i>300</i>
3	6	Front grille clips	\$ 40.00 <i>200</i>
4	6	Front bumper lower grille clips	\$ 40.00 <i>X</i>
5	1	Front carbon fibre bonnet	\$ 2,800.00 <i>aw 1200</i>
6	1	Front left sport headlamp with control unit	\$ 2,200.00 <i>aw 850</i>
7	1	Front right sport headlamp with control unit	\$ 2,200.00 <i>aw 850.</i>
8	4	Front right fender inner cowling clips	\$ 30.00 <i>1200</i>
9	4	Front support panel top garnish clips	\$ 30.00 <i>X</i>
10	1	Front no plate with garnish	\$ 100.00 <i>X</i>
11	2	Front radiator coolant	\$ 100.00 <i>X</i>
12	1	Front air-con gas	\$ 100.00 <i>X</i>
			\$ 10,200.00

Total parts

\$ 21,164.97

TSL Auto Garage
Blk 4 Joo Chiat Complex
#12-1171 Joo Chiat Road
Singapore 420004

SJZ9196D Volkswagen Scirocco

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,400.00 600
2	To putty and spray painting front portion.	\$ 1,400.00 600
3	To check wiring and focus front headlamp.	\$ 50.00 30
4	To remove and install front bonnet lock mechanism.	\$ 80.00 X
5	To remove and install air con system to facilitate the repair and refill gas.	\$ 150.00 X
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 150.00 X
7	To apply anti rust proofing to front affected area.	\$ 140.00 X
8	Towing service.	\$ 100.00 X
Total labour :		\$ 3,470.00

Total parts : \$ 21,164.97

Total labour : \$ 3,470.00

Total repair cost : \$ 24,634.97

Tanpin 92495745
 "wp" 14/1/22 @ 120pm
 4 days
 LBS running after repair

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: