

# A T AUTO CONSULTANT

Blk 113 Tec White Lane #05-650 Singapore 680113  
HP: 8386 8519 EMAIL: atautoconsultant@gmail.com  
Co. Reg. No.: 53368526E

Date of Estimate: 13.01.2022  
Vehicle No: SJF7530R  
Owner: LEE KUN CHUNG  
Date of Accident: 12.01.2022  
Make & Model: HONDA CIVIC TYPE R FD2  
Chassis No: FD2-1401286

Not with out  
L1 Pay &  
Paying After Repair  
6 days

## ESTIMATE FOR ACCIDENT VEHICLE NOS SJF7530R

### PARTS

|    |   |                                     |   |                             |         |                   |      |
|----|---|-------------------------------------|---|-----------------------------|---------|-------------------|------|
| 1  | 2 | Bootlid reflector RH/LH             | @ | \$378.00                    | dis ltr | \$756.00          | Lx   |
| 2  | 1 | Bootlid weatherstrip                |   |                             | dis ltr | \$236.60          | solu |
| 3  | 2 | Bootlid hinges RH/LH                | @ | \$78.40                     | R       | \$156.80          | X    |
| 4  | 2 | Bootlid hinges cover                | @ | \$65.30                     | R       | \$130.60          | X    |
| 5  | 1 | Bootlid lock                        |   |                             | R       | \$198.10          | X    |
| 6  | 1 | Rear bumper                         |   |                             | R       | \$1,089.00        | ✓    |
| 7  | 2 | Rear bumper side brackets RH/LH     | @ | \$65.20                     | dis ltr | \$130.40          | Lx   |
| 8  | 2 | Tail lamp RH/LH                     | @ | \$651.00                    | dis ltr | \$1,302.00        | Lx   |
| 9  | 1 | Rear end panel                      |   |                             | R       | \$563.00          | ✓    |
| 10 | 1 | Rear end panel top garnish          |   |                             | dis ltr | \$178.00          | ✓    |
| 11 | 2 | Rear chassis extender X 4 pcs LH/RH | @ | \$198.20                    | R       | \$396.40          | X    |
| 12 | 1 | Rear exhaust hook                   |   |                             |         | \$56.20           | ?    |
| 13 | 1 | Rear exhaust hook rubber            |   |                             |         | \$35.40           | ?    |
| 14 | 1 | Exhaust heat shield rear            |   |                             |         | \$89.50           | ?    |
| 15 | 1 | Rear fender RH(repair)              |   |                             |         | \$0.00            |      |
|    |   |                                     |   | <b>SUB TOTAL</b>            |         | <b>\$5,318.00</b> |      |
|    |   |                                     |   | <b>LESS 20%</b>             |         | <b>\$1,063.60</b> |      |
|    |   |                                     |   | <b>DISCOUNTED SUB TOTAL</b> |         | <b>\$4,254.40</b> |      |

### S. NETT ITEM

|   |      |                                          |  |                             |         |                    |       |
|---|------|------------------------------------------|--|-----------------------------|---------|--------------------|-------|
| 1 | 1set | Rear bumper clips                        |  |                             | R       | \$60.00            | ✓     |
| 2 | 1set | rear reverse sensor                      |  |                             | R       | \$320.00           | 200in |
| 3 | 1set | Bootlid spoiler mugen X 3 pcs            |  |                             | G-14    | \$1,002.00         | 400?  |
| 4 | 1set | Rear bumper lower diffuser mugen X 3 pcs |  |                             | dis ltr | \$968.00           | ✓     |
| 5 | 1    | Bootlid carbon fiber Japan               |  |                             | CM      | \$3,896.00         | ✓     |
| 6 | 1    | Exhaust system(JC RACING)                |  |                             |         | \$3,985.00         | ?     |
|   |      |                                          |  | <b>SUB TOTAL</b>            |         | <b>\$10,231.00</b> |       |
|   |      |                                          |  | <b>LESS 0 %</b>             |         | <b>\$0.00</b>      |       |
|   |      |                                          |  | <b>DISCOUNTED SUB TOTAL</b> |         | <b>\$10,231.00</b> |       |

### LABOUR

|                    |                                                     |            |      |
|--------------------|-----------------------------------------------------|------------|------|
| 1                  | Panel beating for replace and repair affected parts | \$1,200.00 | 600l |
| 2                  | Spray painting on accdient areas                    | \$900.00   | 800l |
| 3                  | Wiring charges                                      | \$100.00   | 20l  |
| 4                  | Re-alignment of rear chassis                        | \$300.00   | x    |
| 5                  | Apply undercoating to above affected areas          | \$300.00   | 30l  |
| 6                  | Water leakage test after repair                     | \$120.00   | 20l  |
| SUB TOTAL (LABOUR) |                                                     | \$2,920.00 |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- And also subject to confirmation
- Third party survey is compulsory

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: