

# A T AUTO CONSULTANT

Blk 113 Tec Wh Lane #05-650 Singapore 680113  
HP: 8386 85 97 MAIL: atautoconsultant@gmail.com  
Co. Reg. No.: S3368526E

Date of Estimate: 13.01.2022  
Vehicle No: SJF7530R  
Owner: LEE KUN CHUNG  
Date of Accident: 12.01.2022  
Make & Model: HONDA CIVIC TYPE R FD2  
Chassis No: FD2-1401286

Not with out  
61Pm @ 6600h  
Penny After Rain  
6 day

\$250.00 / 1201

## ESTIMATE FOR ACCIDENT VEHICLE NOS SJF7530R

### PARTS

|    |   |                                     |   |                      |                    |      |
|----|---|-------------------------------------|---|----------------------|--------------------|------|
| 1  | 2 | Bootlid reflector RH/LH             | @ | \$378.00             | old car \$756.00   | LT   |
| 2  | 1 | Bootlid weatherstrip                |   |                      | \$236.60           | 501w |
| 3  | 2 | Bootlid hinges RH/LH                | @ | \$78.40              | "                  | X    |
| 4  | 2 | Bootlid hinges cover                | @ | \$65.30              | "                  | X    |
| 5  | 1 | Bootlid lock                        |   |                      | "                  | X    |
| 6  | 1 | Rear bumper                         |   |                      | R1 \$1,089.00      | ✓    |
| 7  | 2 | Rear bumper side brackets RH/LH     | @ | \$65.20              | old car \$130.40   | LT   |
| 8  | 2 | Tail lamp RH/LH                     | @ | \$651.00             | old car \$1,302.00 | LT   |
| 9  | 1 | Rear end panel                      |   |                      | R1 \$563.00        | ✓    |
| 10 | 1 | Rear end panel top garnish          |   |                      | D1 \$178.00        | ✓    |
| 11 | 2 | Rear chassis extender X 4 pcs LH/RH | @ | \$198.20             | "                  | X    |
| 12 | 1 | Rear exhaust hook                   |   |                      | S1 \$56.20         | X    |
| 13 | 1 | Rear exhaust hook rubber            |   |                      | "                  | X    |
| 14 | 1 | Exhaust heat shield rear            |   |                      | "                  | X    |
| 15 | 1 | Rear fender RH(repair)              |   |                      | "                  | X    |
|    |   |                                     |   |                      | \$0.00             |      |
|    |   |                                     |   | SUB TOTAL            | \$5,318.00         |      |
|    |   |                                     |   | LESS 20%             | \$1,063.60         |      |
|    |   |                                     |   | DISCOUNTED SUB TOTAL | \$4,254.40         |      |

### S. NETT ITEM

|   |      |                                          |  |                      |             |            |        |
|---|------|------------------------------------------|--|----------------------|-------------|------------|--------|
| 1 | 1set | Rear bumper clips                        |  |                      | "           | \$60.00    | ✓      |
| 2 | 1set | rear reverse sensor                      |  |                      | "           | \$320.00   | 2001w  |
| 3 | 1set | Bootlid spoiler mugen X 3 pcs            |  |                      | NN          | \$1,002.00 | ✓      |
| 4 | 1set | Rear bumper lower diffuser mugen X 3 pcs |  |                      | NN          | \$968.00   | ✓      |
| 5 | 1    | Bootlid carbon fiber Japan               |  |                      | CM          | \$3,896.00 | ✓      |
| 6 | 1    | Exhaust system(JC RACING)                |  |                      | R1          | \$3,985.00 | 75001w |
|   |      |                                          |  |                      |             | \$0.00     |        |
|   |      |                                          |  | SUB TOTAL            | \$10,231.00 |            |        |
|   |      |                                          |  | LESS 0 %             | \$0.00      |            |        |
|   |      |                                          |  | DISCOUNTED SUB TOTAL | \$10,231.00 |            |        |

### ABOUR

|   |                                                     |            |      |
|---|-----------------------------------------------------|------------|------|
| 1 | Panel beating for replace and repair affected parts | \$1,200.00 | 6001 |
| 2 | Spray painting on accident areas                    | \$900.00   | 8001 |
| 3 | Wiring charges                                      | \$100.00   | 201  |
| 4 | Re-alignment of rear chassis                        | \$300.00   | X    |
| 5 | Apply undercoating to above affected areas          | \$300.00   | 301  |
| 6 | Water leakage test after repair                     | \$120.00   | 201  |
|   |                                                     | \$2,920.00 |      |

LKK Auto Consultants hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• To be subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
• To be subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: