

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22000489/KEA3Q2**Date:** 08/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210143089
Claimant Vehicle No :	SMY3679L	Insured Vehicle No :	SDH1888J
Date of Loss:	10/01/2022	Nature of Claim:	TP
		Claim No:	8226171551SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY3679L		
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID ASCENT (A)	Engine No:	A25A0A29708
Reg. Date:	02/03/2021 (Man. Year: 2020)	Chassis No:	JTNB23HK503075636
Colour:	Metallic Pearl Red	Odometer:	11774 km
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,726.85	3,644.17	2,082.68	36.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,680.00	1,380.00	300.00	17.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,406.85	5,024.17	2,382.68	32.17
+ GST 7.00/7.00% (S\$)	518.48	351.69	166.79	32.17
Nett Amount (S\$)	7,925.33	5,375.86	2,549.47	32.17
+ Car Rental (8.0 x S\$150.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,577.86		

INSPECTION

Date of Assignment:	13/01/2022	
Date Inspected:	13/01/2022	Inspected At: Alan's United Auto Pte Ltd (HQ) Blk 7 Sin Ming Industrial Estate, #01-76 Singapore 575642
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,155.30 FL	*1,122.00 FL
2	1		*BOOT LID LOGO	Necessary	52.20 FL	*52.20 FL
3	1		*BOOT LID HYBRID EMBLEM	Necessary	48.20 FL	*48.20 FL
4	2		*BOOT LID LAMP	Serviceable	760.20 FL	*- FL
5	1		*BOOT LID RUBBER	Cut	204.60 FL	*204.60 FL
6	1		*BOOT LID LOCK HOOK	Repair	38.30 FL	*- FL
7	1		*BOOT LID INNER LOCK	Dented	478.50 FL	*478.50 FL
8	2		*TAILLAMP	Serviceable	1,234.60 FL	*- FL
9	1		*REAR END PANEL	Bent	581.20 FL	*581.20 FL
10	1		*END PANEL TOP GARNISH	Buckled	325.80 FL	*325.80 FL
11	1		*SPARE TYRE BOARD	Deformed	555.60 FL	*555.60 FL
12	1		*REAR BUMPER FASCIA	Buckled	742.20 FL	*742.20 FL
13	1		*REAR BUMPER LOWER LIP	Serviceable	466.10 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	420.20 FL	*420.20 FL
15	2		*REAR BUMPER SIDE RETAINER	Serviceable	244.40 FL	*- FL
16	2		*REAR BUMPER LOWER GARNISH	Cracked	205.60 FL	*205.60 FL
17	2		*REAR BUMPER PARKING SENSOR BRACKET	Necessary	56.40 FL	*56.40 FL
18	2		*TAILLAMP COVER	Dented	66.40 FL	*66.40 FL
					Sub Total (S\$)	7,635.80 4,858.90
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,908.95 1,214.73
					Total Parts (S\$)	5,726.85 3,644.17

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
2	TO APPLY UNDERSEALING	New	60.00	60.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	800.00	660.00
4	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN REFIX AND TO RENEW ABOVE PARTS	New	700.00	600.00
Gross Labour Cost (\$)			1,680.00	1,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >