



BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBN3215E model: honda fs150f

Handle Bar	X	135
Handle Balance	X	55
Clutch Lever	—	85
Signal Light F-L-H	—	85
Mudguard	—	135
Footrest F-L-H	—	90
Footrest Holder F-L-H	X	80
Gear Paddle	—	85
Footrest R-L-H	X	90
Signal Light R-L-H	—	85
Signal Light R-R-H	X	85
Rear Rim	X	480
Side Cover	—	165
Rear Box		185
Rear Carrier	X	145
Mirror	—	80
IU Unit	—	165
Front Fork Alignment	X	350
Rear Body Frame Repair	X	350
Rear Brake Disc	X	180
Rear Wheel Shaft	X	185
Labour		350
Towing	X	50
total		3695

2 Days.

L/S

After repair photos.

Eric Rief

14/1/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: