



BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBN3215E model: honda fs150f

Handle Bar X *Spn*
 Handle Balance X
 Clutch Lever *cut*
 Signal Light F-L-H *Dis*
 Mudguard *cut*
 Footrest F-L-H *cut*
 Footrest Holder F-L-H X *nn*
 Gear Paddle *cut*
 Footrest R-L-H X *nn*
 Signal Light R-L-H *Dis*
 Signal Light R-R-H X *nn*
 Rear Rim X *Repair*
 Side Cover *cut*
 Rear Box *✓ CUT*
 Rear Carrier X
 Mirror *cut*
 IU Unit *cut*
 Front Fork Alignment X *nn*
 Rear Body Frame Repair X *nn*
 Rear Brake Disc X
 Rear Wheel Shaft X
 Labour
 Towing X *nn*
 total

135	
55	
85	48
85	55
135	65
90	40
80	
85	48
90	
85	55
85	
480	
165	90
185	150(SN)
145	
80	65
165	✓(SN)
350	
350	466
180	-10%: 419.4
185	934.4
350	15 . 200
50	X
3695	-20%: 750

2 Days.
L/S
After repair photos.
Erica Riep
14/1/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____