

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/1988 GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22000494/Aqy3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Г	Date:	03/02/2023	
			C	Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLB 8037P	Veh. Inspected		SLZ 3271K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C1001337/JM	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		13/01/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA SHUTTLE	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	GK81201285	Colour		WHITE	
	Odometer	52716 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/60 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195/60 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195/60 R15	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195/60 R15	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	12/01/2022	Inspection Date		13/01/2022	
	Survey held at	ACE AUTOLUTION PTE LTD				
		13 KAKI BUKIT ROAD 4 #03-29 BARTLEY BIZ CENTRE SINGAPORE 417807				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

12 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: