

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR ADJUSTMENT
	PARTS (LIST ITEMS)			
1	REAR BUMPER <i>Distorted.</i>		1218.70	985
2	REAR BUMPER SIDE RETAINER LH & RH @\$68.20 <i>Damd.</i>		136.40	✓
2	REAR BUMPER SIDE GARNISH LH & RH @\$104.10 <i>LH Dehd</i>		208.20	104.10
2	REAR BUMPER BRACKET LH & RH @\$85.60 <i>new</i>		171.20	X
2	REAR BUMPER SPONGE LH & RH @\$103.50 <i>new</i>		207.00	X
1	REAR BUMPER TOW COVER <i>Dehd</i>		40.00	✓
1	REAR SMART BUZZLE <i>new</i>		155.00	X
1	REAR ANTENNA KEYLESS		250.00	X
1	REAR TAILGATE <i>Distorted</i>		1292.70	1193.
1	REAR TAILGATE INNER LOCK <i>Damd.</i>		378.00	✓
1	REAR TAILGATE INNER TRIMBOARD <i>Dehd</i>		410.00	325
2	REAR TAILGATE DAMPER LH & RH @\$300.00 <i>new</i>		600.00	X
1	REAR TAILGATE "SHUTTLE" EMBLEM <i>new</i>		72.00	✓
1	REAR TAILGATE "HYBRID" EMBLEM <i>new</i>		80.10	✓
1	REAR TAILGATE LOGO <i>new</i>		75.00	✓
1	REAR TAILGATE CENTRE CHROME <i>new</i>		405.00	✓
1	REAR TAILGATE WEATHERSTRIP <i>new</i>		232.80	✓
2	REAR TAILGATE LAMP LH & RH @\$434.50 <i>new</i>		869.00	✓
2	REAR TAILGATE LAMP LH & RH @\$578.00 <i>new</i>		1156.00	✓
2	REAR TAILGATE PANEL LH & RH @\$225.90 <i>LH Dented</i>		451.80	225.90
1	REAR LUGGAGE COMPARTMENT <i>new</i>		1980.00	X
1	REAR END PANEL <i>Distorted</i>		620.00	✓
1	REAR END PANEL TOP GARNISH <i>Dehd</i>		222.00	✓
1	REAR SPARE TYRE WELL PANEL <i>new</i>		1003.80	✓
1	REAR SPARE TYRE BOARD <i>Dehd</i>		687.80	585
1	REAR WINDSCREEN MOULDING <i>new</i>		120.00	✓
1	REAR WIPER <i>new</i>		101.00	X
1	REAR WIPER MOTOR		355.00	X
2	REAR FENDER LH & RH @\$1060.90 <i>LH Buckled</i>		2121.80	1060.90
2	REAR FENDER INNER TRIM LH & RH @\$549.60 <i>Dehd.</i>		1099.20	788.
	<i>Tools Tray Dehd 385. ✓</i>			
		less	16719.50	
			20%	20%
			3343.90	
			13375.60	
	SPECIAL NETT ITEMS			
1 SET	REVERSE SENSOR <i>new</i>		280.00	200.
1	REVERSE CAMERA		380.00	✓
1 SET	REAR BUMPER CLIPS <i>new</i>		60.00	30.
1	REAR END PANEL SEALANT <i>new</i>		100.00	60.
1 SET	REAR CAR PLATE WITH CASING <i>new</i>		75.00	X
1 SET	REAR TAILGATE INNER TRIM CLIPS <i>new</i>		80.00	30.
1 SET	REAR END PANEL TOP GARNISH CLIPS <i>new</i>		60.00	20.
1	REAR WINDSCREEN SEALANT <i>new</i>		100.00	60.
	Total Parts		14510.60	



ACE AUTOLUTION PTE LTD

13 Kaki Bukit Road 4 Bartley Biz Centre #03-29

Singapore 417807

Tel:6702 4282 Fax:6702 4202

Vehicle No. SLZ3271K HONDA SHUTLE

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
LABOUR			
1	To remove the affected parts & fittings to commence repairs and replace damaged parts	2000	1600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	2000	1300
3	To remove and refix wiring at damaged areas	180.00	30
4	To perform anti rust treatment on affected areas	150.00	120
5	To remove and replace reverse sensor and reverse camera nd check for proper function	150.00	100
6	To remove and refix rear windscreen	120.00 ✓	
7	To conduct water sepage test	100.00 X	
8	To transfer rear boot mechanism	120.00	80
9	To tuff coat	150.00	120
10	To remove and refix rear spare tyre, spare tyre board, carpet trim to assist work load	180.00	120
Labour Total :		3950.00	
TOTAL (PARTS & LABOUR):		18460.60	

3590

total 13228.40

L/S: 10.5K.

12 Days.

10.5K