

13/01/2022

1st



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : SMJ7679PMake & Model : TOYOTA PRIUSYear of Manufacture : 2018Chassis No. : JTDKB3FU103080017Ins Company : III VS CHINA TAIPIING

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 1/9/2022

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor : _____

Repair Estimates

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 3,403.60

Contact No : _____

Plus/Less 10% \$ 340.36

Frt Counter Operation : _____

Total of Cost / List \$ 3,063.24

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani tel: 63837890 email: rohanim@sparkcarcare.com

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -Total Parts Cost (Appendix A) \$ 3,063.24Labour (Appendix B) \$ -Total Repair Cost \$ 3,063.24

4363.24

The above total will be subjected to 7% G.S.T.

Back-end Operation
 Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com
 Patrick Tel: 63837466 email: patricktia@sparkcarcare.com

Not Authorized
Returning Repair
8824055

Name of Surveyor : Kenneth
 Company : CKK
 Survey conducted on : 14/1/22 at _____

Remarks By Surveyor(a) The repair of this vehicle is authorized / is not authorized until further notice.(b) Recommended Days of Repair : 03 day(s)(c) Resurvey : Required / Not Required

(d) Excess \$ _____

(e) Signature of surveyor : De Date: 14/1/22

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Page 1

Spare Parts

Vehicle No : SMJ7679P Case Owner : 0
Make & Model : TOYOTA PRIUS Year Manufacture : 2018
Chassis No : JTDKB3FU103080017 Engine No : 0
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1	<i>Am</i>	\$ 556.70			<input checked="" type="checkbox"/>
2	REAR BUMPER SIDE RETAINER LH	1	<i>Am</i>	\$ 117.30			<input checked="" type="checkbox"/>
3	REAR BUMPER SIDE RETAINER RH	1	<i>Am</i>	\$ 117.30			<input checked="" type="checkbox"/>
4	REAR BUMPER REINFORCEMENT	1	<i>Am</i>	\$ 339.70			<input checked="" type="checkbox"/>
5	REAR BUMPER LOWER	1	<i>Edm</i>	\$ 586.70			<input checked="" type="checkbox"/>
6	REAR BUMPER SENSOR	2	<i>Am</i>	\$ 576.00			<input checked="" type="checkbox"/>
7	REAR BUMPER CLIPS	10	<i>Am</i>	\$ 57.80			<input checked="" type="checkbox"/>
8	TAILGATE GARNISH	1	<i>Am</i>	\$ 925.60			<input checked="" type="checkbox"/>
9	TAILGATE EMBLEM HYBRID	<i>Am</i> 1	<i>Am</i>	\$ 64.30			<input checked="" type="checkbox"/>
10	TAILGATE EMBLEM PRIUS	<i>Am</i> 1	<i>Am</i>	\$ 62.20			<input checked="" type="checkbox"/>
11	0	1					
12	0	1					
13	0	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
1	0	0					
2	0	0					
3	0	0					
4	0	0					
5	0	0					
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

13/01/2022

4:32 PM

Alt Gr 

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. : SMJ7679P
Make & Model : TOYOTA PRIUS

Case Owner	0
Year of Manufacture	2018

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged parts during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 	
<p>Acknowledged by Repairer</p> <p>Signature: _____</p> <p>Date: _____</p>	

26 1