

13/01/2022



ComfortDelGro Engineering

205 Braddell Road S(579701)

1st

Our Ref:

ACCIDENT REPAIR ESTIMATES

Type of Claim : TP

Vehicle No. : SMJ7679P

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2018

Chassis No. : JTDKB3FU103080017

Engine No. : _____

Policy No. : _____

Time of Accident : _____

In-house Vehicle Assessor

Case Owner : _____

Signature : _____

Contact No
Frt Counter Operation

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Rohani tel: 63837890 email: rohanim@sparkcarcare.com

Back-end Operation

Ngo Toh Wee Tel: 63837656 email: ngotw@sparkcarcare.com

Patrick Tel: 63837466 email: patricktia@sparkcarcare.com

Repair Estimates

Parts (a) Cost / List Price Items \$ 3,403.60

Plus/Less 10% \$ 340.36

Total of Cost / List \$ 3,063.24

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 3,063.24

Labour (Appendix B) \$ -

Total Repair Cost \$ 3,063.24 **4363.24**

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : CKK
Survey conducted on : 14/1/22 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : [Signature] Date: 14/1/22

Not Authorised
Returning B4 pricing
82145-68

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Page 1

Spare Parts

Vehicle No : SMJ7679P Case Owner : 0
Make & Model : TOYOTA PRIUS Year Manufacture : 2018
Chassis No : JTDKB3FU103080017 Engine No : 0
Sales Order : _____ Supplier : _____
Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	REAR BUMPER	1	<i>PL</i>	\$ 556.70			<input checked="" type="checkbox"/>
2	REAR BUMPER SIDE RETAINER LH	1	<i>PL</i>	\$ 117.30			<input checked="" type="checkbox"/>
3	REAR BUMPER SIDE RETAINER RH	1	<i>PL</i>	\$ 117.30			<input checked="" type="checkbox"/>
4	REAR BUMPER REINFORCEMENT	1	<i>PL</i>	\$ 339.70			<input checked="" type="checkbox"/>
5	REAR BUMPER LOWER	1	<i>Red 17.1</i>	\$ 586.70			<input checked="" type="checkbox"/>
6	REAR BUMPER SENSOR	2	<i>PL</i>	\$ 576.00			<input checked="" type="checkbox"/>
7	REAR BUMPER CLIPS	10	<i>PL</i>	\$ 57.80			<input checked="" type="checkbox"/>
8	TAILGATE GARNISH	1	<i>PL</i>	\$ 925.60			<input checked="" type="checkbox"/>
9	TAILGATE EMBLEM HYBRID	1	<i>NN</i>	\$ 64.30			<input checked="" type="checkbox"/>
10	TAILGATE EMBLEM PRIUS	1	<i>NN</i>	\$ 62.20			<input checked="" type="checkbox"/>
11	0	1					
12	0	1					
13	0	1					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

13/01/2022

4:32 PM

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No. .

Make & Model : SMJ7679P
TOYOTA PRIUS

: 0

2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.