

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22000496/AEA3Q2**Date:** 13/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0008535
Claimant Vehicle No : SLQ2999Z **Insured Vehicle No :** XE1180X
 Date of Loss: 11/01/2022 Nature of Claim: TP Claim No: MFL2022D0000471

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLQ2999Z**
 Make & Model: MERCEDES-BENZ 190E, 2.3 16V W20 (M) Engine No: 10298320009611
 Reg. Date: 19/11/1985 (Man. Year: 1985) Chassis No: WDB2010342F158982
 Colour: Black Odometer: 128591 km
 Engine Capacity: 2299 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,649.30	10,105.30	2,544.00	20.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,480.00	3,430.00	1,050.00	23.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,129.30	13,535.30	3,594.00	20.98
Approved Total (Overridden) (S\$)		10,800.00		
(S\$)	17,129.30	10,800.00	6,329.30	36.95
+ GST 7.00/7.00% (S\$)	1,199.05	756.00	443.05	36.95
Nett Amount (S\$)	18,328.35	11,556.00	6,772.35	36.95
+ Loss of Use (12.0 x S\$100.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,763.45		
Global Sum Settlement (S\$)		12,760.00		

INSPECTION

Date of Assignment: 13/01/2022
 Date Inspected: 13/01/2022 Inspected At: Modern Automotive Pte Ltd (HQ)
 Estimated Period of Repair: 10.0 days Blk 3023A Ubi Road 1, #01-61 & #01-58
 Singapore 408717

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 May 2022)
Parts:	143	MERCEDES-BENZ 190E 2.3 16V W20 (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ2999Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR NUMBER PLATE LAMP -LH & RH	Cracked	90.00 FL	*90.00 FL
2	1		*REAR BUMPER	Distorted	1,255.00 FL	*1,255.00 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	78.00 FL	*78.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	459.00 FL	*459.00 FL
5	1		*REAR END PANEL	Distorted	820.00 FL	*820.00 FL
6	1		*REAR END PANEL TOP GARNISH	Cracked	249.00 FL	*249.00 FL
7	2		*TAIL LAMP -LH & RH	Cracked	950.00 FL	*950.00 FL
8	2		*TAIL LAMP BACK COVER-LH & RH	Cracked	170.00 FL	*170.00 FL
9	1		*TAIL LAMP PANEL	Dented	515.00 FL	*515.00 FL
10	1		*BOOTLID	Distorted	1,450.00 FL	*1,450.00 FL
11	1		*BOOTLID LOCK	Jammed	268.00 FL	*268.00 FL
12	1		*BOOTLID WEATHERSTRIP	Cut	249.00 FL	*249.00 FL
13	2		*BOOTLID HINGES -LH & RH	Bent	278.00 FL	*278.00 FL
14	1		*MERCEDES BENZ LOGO	Necessary	65.00 FL	*65.00 FL
15	1		*190E EMBLEM	Necessary	85.00 FL	*85.00 FL
16	1		*2.5 EMBLEM	Necessary	95.00 FL	*95.00 FL
17	1		*REAR FENDER -LH & RH	N/S Repair / O/S Distorted	2,530.00 FL	*1,265.00 FL
18	2		*REAR FENDER INNER TRIM BOARD -LH & RH	Cracked	788.00 FL	*788.00 FL
19	1		*SPARE TYRE PANEL	Repair	1,195.00 FL	*- FL
20	1		*SPARE TYRE PANEL TOP COVER	Cracked	288.00 FL	*288.00 FL
21	1		*REAR NUMBER PLATE	Cracked	30.00 FS	*30.00 FS
22	1		*REAR NUMBER PLATE HOLDER	Cracked	30.00 FS	*30.00 FS
23	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
24	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
25	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
26	1		*BOOTLID TOP SPOILER	Cracked	1,500.00 FS	*1,200.00 FS
27	1		*REAR FENDER LOWER TRIM BOARD CLIPS	Necessary	60.00 FS	*60.00 FS
28	1		*EMERGENCY SIGNAGE	Bent	150.00 FS	*120.00 FS
29	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,837.00	11,047.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,187.70	941.70
Total Parts (\$\$)	12,649.30	10,105.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	2,000.00	1,600.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,600.00	1,400.00
3	TO CHECK WIRING	New	100.00	30.00
4	TO SPRAY TUFF COAT	New	300.00	120.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
7	TO REMOVE REAR WINDSCREEN	New	180.00	120.00
Gross Labour Cost (\$)			4,480.00	3,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >