

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

AYADI BIN AZLI
BLK 619A TAMPINES ST 61 #05-580
SINGAPORE 521619

Contact : 96879458

TAX INVOICE

Repair Code : CLM15415

Date in : 12/01/2022

Vehicle Num. : SMV6184T

Model : HONDA FIT 1.3 BASIC AUTO

Chassis/Eng# : GR11001056/L13B1501960

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>del</i>	1	1210.25	<i>950</i> 1,210.25
REAR BUMPER REFLECTOR L/R <i>new</i>	2	55.00	<i>+</i> 110.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	20.80	<i>✓</i> 41.60
REAR END PANEL <i>del</i>	1	711.40	<i>545</i> 711.40
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	80.80	<i>✓</i> 80.80
REAR END PANEL BUZZLE SENSOR <i>del</i>	1	85.20	<i>✓</i> 85.20
REAR END PANEL INNER TOP GARNISH <i>del</i>	1	120.35	<i>✓</i> 120.35
REAR TAILGATE <i>del</i>	1	1473.75	<i>1036</i> 1,473.75
REAR TAILGATE 'FIT' EMBLEM <i>new</i>	1	45.70	<i>✓</i> 45.70
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	28.70	<i>+</i> 28.70
REAR TAILGATE INNER TRIM GARNISH <i>new</i>	1	301.30	<i>+</i> 301.30
REAR TAILGATE MECHANISM LOCK <i>del</i>	1	355.80	<i>295</i> 355.80
REAR TAILGATE RUBBER GUIDE STOPPER <i>new</i>	2	25.00	<i>+</i> 50.00
REAR TAILGATE WEATHER STRIP RUBBER <i>del</i>	1	147.30	<i>✓</i> 147.30
REAR TAILGATE WINDSCREEN LOWER MOULDING <i>new</i>	1	55.20	<i>✓</i> 55.20
REAR TAILGATE WINDSCREEN SIDE MOULDING L/R <i>new</i>	2	25.10	<i>✓</i> 50.20
REAR TAILGATE WINDSCREEN TOP MOULDING <i>new</i>	1	53.50	<i>✓</i> 53.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

AYADI BIN AZLI
 BLK 619A TAMPINES ST 61 #05-580
 SINGAPORE 521619

Contact : 96879458

TAX INVOICE

Repair Code : CLM15415

Date in : 12/01/2022

Vehicle Num. : SMV6184T

Model : HONDA FIT 1.3 BASIC AUTO

Chassis/Eng# : GR11001056/L13B1501960

		Subtotal before discount	4,921.05
Percentage discount 20%			984.21
		Sub-total 1	3,936.84
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR BUMPER REVERSE SENSOR - SET	1	250.00	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00
REAR TAILGATE WINDSCREEN SEALANT	1	60.00	60.00
		Subtotal before discount	440.00
Percentage discount 0%			0.00
		Sub-total 2	440.00
		Parts-total	4,376.84

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total

Parts & Labour Total

2,790.00

7,166.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer

Signature

*** This is a computer-generated document which requires no signature.***

page 2

06 Days
 total: 5064.68
 2/s: 4K