

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Address : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

Steve (LKK)
 19/1/22, 9.30am

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
 Motor Claims Dept

Date : 14 Jan 2022

Dear Sirs :

Fax : 6224 1047

RE : ESTIMATE COST FOR NISSAN TEANA 2.0 - SJP6594K
ACCIDENT INVOLVING SJP6594K & SKS7001X ON 12/01/2022

ITEMS	DESCRIPTION	QTY	PRICE
1	Rear bumper — BR	1pc	\$ 935.00
2	Rear bumper retainer o/s — BR	1pc	\$ 40.00
3	Rear bumper outer moulding o/s — CM	1pc	\$ 474.00
4	Rear lamp o/s — BR	1pc	\$ 645.00
5	Rear mudguard o/s ? X R	1pc	\$ 1,280.00
			\$ 3,374.00
	Less 30%		\$ (1,012.20)
	10%		\$ 2,361.80
	Labour Charge & Misc		
	To remove, replace, repair & weld rear damaged parts.		\$ 800.00
	To R & R sensor wiring		\$ 100.00
	To R & R light wiring.		\$ 60.00
	To putty & spray painting		\$ 700.00
	Total		\$ 4,021.80

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: