



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2203629

INV Date 13/06/2022

Reference CC4/LPC22000503/Vea3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLZ 1220X
Insured Veh. YP 5887U
Claim No. 21/22/22/VC00/025356
Policy No. Z/21/VC00/112460
Accident Date 10/01/2022
Inspection Date 20/01/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22000503/Vea3q2 Date: 13/06/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 5887U	Veh. Inspected	SLZ 1220X	
Policy No.	Z/21/VC00/112460	Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025356	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	13/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	MR053REH604581265	Colour	GREY	
Odometer	73879 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
L/H Front Tyre	215/45 R17	GOODYEAR	6 mm	
R/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
L/H Rear Tyre	215/45 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/01/2022	Inspection Date	20/01/2022	
Survey held at	YONG SING MOTOR WORKS 10 DEFU LANE 8 DEFU INDUSTRIAL ESTATE SINGAPORE 539315			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 1220X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	DENTED	1,650.00	1,140.40
1	FRONT BONNET LH HINGE	SHORTED	395.00	78.50
1	FRONT BONNET CHROME GARNISH	SCRATCHED	425.00	189.20
1	FRONT BONNET INSULATION	SERVICEABLE	410.00	-
1	FRONT SUPPORT PANEL	SERVICEABLE	850.00	-
1	FRONT LH HEADLAMP	SCRATCHED	1,850.00	1,850.00
1	FRONT BUMPER	DENTED	1,460.00	489.60
1	FRONT LH RETAINER	NECESSARY	340.00	105.10
1	FRONT LH FOGLAMP	SERVICEABLE	430.00	-
1	FRONT LH FOGLAMP COVER	SCRATCHED	385.00	112.90
1	FRONT GRILLE	SCRATCHED	675.00	466.10
	LESS 25% DISCOUNT		-2,217.50	-1,107.95
			6,652.50	3,323.85
	<u>LABOUR</u>			
	TO REMOVE AND REPLACE DAMAGED ITEMS REALIGN FRONT VEHICLE FRAME.		1,500.00	800.00
	SPRAY PAINT FRONT BONNET & UNDERSIDE.		450.00	200.00
	SPRAY PAINT LH FENDER .		350.00	200.00
	SPRAY PAINT FRONT BUMPER .		400.00	200.00
	DOOR LH .		200.00	200.00
	TO CONDUCT SYSTEM WIRING CHECK .		100.00	30.00
	TP PROVIDE ANTI RUST COATING.		150.00	50.00
			3,150.00	1,680.00
	GRAND TOTAL		9,802.50	5,003.85
	RECOMMENDED COST OF REPAIRS			5,003.85

Report Ref No. CC4/LPC22000503/Vea3q2

THEVAN THOMAS KARTHIKESAVAN

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 1220X

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLZ 1220X

RE-INSPECTION

