


Yong Sing Estimate Repair

Vehicle Registration Number SLZ1220ZX
Make / Model TOYOTA ALTIS
Chassis No. _____
Year of Manufacture _____
Registration Date _____
Type of Repair (TP/OD/WS) TP
Date/Time of Accident 10/1/2022 20:15:00 PM
Rental Vehicle Yes / No
Remark _____

Case Ref No. INS00113

The damages on the vehicle are as indicated in the following diagram.



	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ 1,500.00	\$ -
Total Spray Painting Cost	\$ 1,200.00	\$ -
Total Spare Parts Cost	\$ 6,652.50	\$ -
Other Charges	\$ 250.00	\$ -
TOTAL	\$ 9,602.50	\$ -
Lump Sum Repair, if any :		\$ -
No. of Repair Days	[6] days	[] days

Surveyor Remark:

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REMOVE AND REPLACE DAMAGED ITEMS. REALIGN FRONT VEHICLE FRAME	\$1,500.00	800
Total Labour Cost	\$1,500.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
SPRAY PAINT FRONT BONNET & UNDERSIDE	\$450.00	200
SPRAY PAINT LH FENDER	\$350.00	700
SPRAY PAINT FRONT BUMPER	\$400.00	200
Door LH		200
Total Spray Painting Cost	\$1,200.00	\$0.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO CONDUCT SYSTEM WIRING CHECK	\$100.00	30
TO PROVIDE ANTI RUST COATING.	\$150.00	50
Total Other Costs	\$250.00	\$0.00

Thevan@lkhauto.com

8223 8769

20/1/22 1730

wp 6 days

PIP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	List Price (\$)	Discount (25%)	Final Price (\$)	Repair # Replace (/) Yrsg Surd	Repair # Replace (/) Subpart
1	FRONT BONNET		1	\$ 1,650.00	25%	\$ 1,237.50	REPLACE (/)	/ DT
2	FRONT BONNET LH HINGE		1	\$ 395.00	25%	\$ 296.25	REPLACE (/)	/ sh
3	FRONT BONNET CHROME GARNISH		1	\$ 425.00	25%	\$ 318.75	REPLACE (/)	/ SCR
4	FRONT BONNET INSULATION		1	\$ 410.00	25%	\$ 307.50	REPLACE (/)	/ XGVC
5	FRONT SUPPORT PANEL		1	\$ 850.00	125%	\$ 637.50	REPLACE (/)	/ XGVC
6	FRONT LH HEADLAMP		1	\$ 1,850.00	25%	\$ 1,387.50	REPLACE (/)	/ SCR
7	FRONT BUMPER		1	\$ 1,460.00	25%	\$ 1,095.00	REPLACE (/)	/ DT
8	FRONT LH RETAINER		1	\$ 340.00	125%	\$ 255.00	REPLACE (/)	/ XGVC
9	FRONT LH FOGLAMP		1	\$ 430.00	25%	\$ 322.50	REPLACE (/)	/ XGVC
10	FRONT LH FOGLAMP COVER		1	\$ 385.00	25%	\$ 288.75	REPLACE (/)	/ SCR
11	FRONT GRILLE		1	\$ 675.00	25%	\$ 506.25	REPLACE (/)	/ SCR
TOTAL MATERIAL: \$ 8,870.00						\$ 6,652.50		

1140.4
485
189.2
489.6
105.1
112.9
466.1