



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2303807

INV Date 15/06/2023

Reference CC4/LPC22000504/Kya3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. GBA 3374Y

Insured Veh. YQ 1276D

Claim No. 21/22/22/VC05/025360

Policy No. Z21VC05008384

Accident Date 11/01/2022

Inspection Date 08/03/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CC4/LPC22000504/Kya3q2 Date: 15/06/2023 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YQ 1276D	Veh. Inspected	GBA 3374Y	
Policy No.	Z21VC05008384	Coverage (\$)	0.00	
Claim No.	21/22/22/VC05/025360	Excess (\$)	0.00	
Assign From	ENG HUEY NI	Assign Date	13/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JTFAT35Y103000896	Colour	BLUE	
Odometer	496738 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	MICHELIN	4 mm	
L/H Front Tyre	195 R15X8	MICHELIN	4 mm	
R/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	8/8 mm	
L/H Rear Tyre	155 R12X8 (D)	YOKOHAMA	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/01/2022	Inspection Date	08/03/2022	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBA 3374Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE	BENT	1,116.70	1,116.70
	LESS 25% DISCOUNT		-279.18	-279.18
			837.52	837.52
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE STICKER '70KM/HR' (SN)	NECESSARY	15.00	15.00
1	TAILGATE ADVERTISEMENT STICKER (SN)	NECESSARY	250.00	180.00
			265.00	195.00
	<u>LABOUR</u>			
	REMOVE & REFIX REAR TAILGATE & ATTACHMENTS KNOCKING & REPAIR REAR FLOORBOARD & REALIGN THE SAME.		400.00	350.00
	PUTTY & RESPRAY REAR TAILGATE ,REAR FLOOR BOARD & ALL AFFECTED AREAS .		500.00	400.00
	RUSTPROOFING.		30.00	30.00
			930.00	780.00
	GRAND TOTAL		2,032.52	1,812.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,450.00

Report Ref No. CC4/LPC22000504/Kya3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 3374Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBA 3374Y

RE-INSPECTION

