

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBA3374Y
7P/Layac

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388 FAX: 62963767
ATTN: Motor Claim Department
WS Ref: TP/LONPAC/AMK
Claim Type: Third Party
Accident Date: 11/01/2022
TP Veh Reg No: YQ1276D

Estimate No: ES2290212
Date: 08 Mar 2022
Policy No: 5122046810
Veh Reg No: GBA3374Y
Make/Model: TOYOTA DYNA 150 M
Chassis No: JTFAT35Y103000896
Engine No: 1KD1636268
Reg. Date: 23/05/2007

Estimate Repair Cost to Vehicle No :GBA3374Y

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR TAILGATE	1,116.70	1 PC	1,116.70	
		Less 25%	279.18	837.53
Special Net				
2 TAILGATE STICKER '70KM/HR'	15.00	1 PC	15.00	
3 TAILGATE ADVERTISEMENT STICKER	250.00	1 PC	250.00	
			265.00	265.00
Labour				
4 REMOVE & REFIX REAR TAILGATE & ATTACHMENTS;KNOCKING & REPAIR RAER FLOORBOARD & REALIGN THE SAME	400.00	1 LA	400.00	350
5 PUTTY & RESPRAY REAR TAILGATE,REAR FLOORBOARD,& ALL AFFECTED AREAS	500.00	1 LA	500.00	400
6 RUSTPROOFING	30.00	1 LA	30.00	
			930.00	930.00
			Total	S\$ 2,032.53
			Add GST @ 7%	142.28
			Total Amount Payable	S\$ 2,174.81

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

Not Withain
11 Pys @ 1450.

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey After Paint
3 days