

TP China
Xiao Chan.

GBK37719 2020 June

Toyota Hiace 2982cc

JTFHTD2P000250124

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: 30(SN)

Date:

Front Number Plate	Best	
Front Bumper	Del'd	580.60 ✓
Front Bumper Clips	per	30(SN) ✓
Front Bumper Side Holder x02	per	65 x 2 = 130 +
Front Bumper Lower Grille	Del'd	166.20 ✓
Front Bumper Lower Cover	per	20.80 +
Front Bumper Side Grille x02	Del'd	66.5 x 2 = 133 ✓
Front Bumper Reinforcement	Best	355.80 ✓
Front Bumper Reinforcement Bracket x02	Best	155 x 2 = 310 ✓
Front Bumper Beam	Best	215.40 ✓
Front Bumper Bracket x02	Best	125.6 x 2 = 251.20 ✓
Front Grille Base	Caul'd	457.20 ✓
Front Grille Upper Garnish		281.50 ✓
Front Grille Lower Garnish		330.80 ✓
Front Grille Clips	per	20(SN) ✓

GBK37716.

Headup x 02	Cracked	753.7 x 2 = 1507.40 ✓
Bonnet	Distorted	872.90 ✓
Bonnet Lock	Dmg	88.90 ✓
Bonnet Hinge x 02	AP	56 x 2 = 112 +
Bonnet Logo.	new	75 ✓
Front Support Panel	Bushed	464.20 ✓
Front Support Panel Garnish.	Del'd	187.40 ✓
Front Support Panel Garnish Clips.	new	20 (SN) ✓
Front Corner Panel x 02	RT Bush'd	376.5 x 2 = 753 376.50
Intercooler	Dented	1289 ✓
Intercooler Air Guide	Del'd	139.40 ✓
Air Con Condenser	Bent	1216.10 ✓
Air Con Liquid Pipe.	Bent	205.60 ✓
Radiator	Dented	1495 ✓
Radiator Spare Tank.	crushed	140.90 ✓
Radiator Coolant	new	40 (SN) ✓
Wiper Washer Tank.	Del'd	188.30 ✓
Fan Cowling	crushed	295 ✓

GBK37719.

Rear Number Plate.	Bent	30(SN) ✓
Rear Number Plate Lap x 02	NH mm	$67.8 \times 2 = 135.60$ ✓
Rear Bumper	Distorted	695.90 ✓
Rear Bumper Clips	per	30(SN) ✓
Rear Bumper Side Holder x 02	Dented	$60.2 \times 2 = 120.40$ ✓
Rear Bumper Lower Bracket x 02	Bent	$30 \times 4 = 120$ ✓
Reverse Sensor	Damaged	280(SN) 200(SN) ✓
Rear End Panel outer	Distorted	388.30 ✓
Rear End Panel Inner		859.50 ✓
Rear End Panel Top Metal Strip	Bent	180.70 ✓
Rear End Panel Sealant	per	60(SN) ✓
Taillamp x 02	Cracked	$395.8 \times 2 = 791.60$ ✓ 461.90
Taillamp Panel x 02	RH Dented	$461.9 \times 2 = 923.80$ ✓ 391.40
Taillamp Panel Inner x 02	RH Dented	$391.4 \times 2 = 782.80$ ✓
Taillamp Lower Apron x 02	Dented	$88.6 \times 2 = 177.20$ ✓
Tailgate	Distorted	1890.50 ✓
Tailgate Lock	Jammed	235.40 ✓
Tailgate Lock Striker	Bent	68.60 ✓
Tailgate Lock Actuator	Damaged	290.90 ✓

GBK3771 G.

Tailgate Weatherstripe. ^{cut}	395.90. —
Tailgate Outer Moulding. ^{del}	364.70 —
Tailgate Outer Handle ^{Dem'd}	85.40 —
Tailgate Inner Trim Board ^{torn}	186.70. —
Tailgate Inner Trim Board clips ^{re}	30(SN) —
Tailgate Hinge x 02 ^{Bent}	89.5 x 2 = 179 —
Tailgate Damper x 02 ^{Dem'd}	287.9 x 2 = 575.80. —
Tailgate Wiper Arm. ^M	98.20 +
Tailgate Wiper Motor ^{Dem'd}	432.10. —
Tailgate Glass Shattered	1115.20. —
Tailgate Glass Moulding ^{2 per}	172.50 —
Tailgate Glass Sealant	60(SN) —
Tailgate Wiper Motor Cover. ^{Del'd}	249.60 —
Toyota Logo. ^{See}	65.90 —
Rear Camera. ^{Dem'd}	480(SN) 380(SN)
Rear RH Body Panel ^{Buckled}	2219.40 —
Rear RH Body Inner Panel. ^{Pyri}	1069.10 +.

GBK3771G.

		145.30
Rees Body Panel Inner Trim Board x22	RH torn	145.3 x 2 = 290.60
Rees Body Panel Inner Trim Board Clips.	mm	60(SN) 30(SN)
Rees RH Wheel Housing Panel.	Rees	1114.70 +
Rees RH Wheel Housing Carpentry Furniture	Rees	450(SN) 350(SN)
Floor Panel	Rees	1850.50 +
Floor Panel Top Board	torn	580(SN) 480(SN)
Floor Panel Carpet	torn	680(SN) 350(SN)
Spare Tyre	mm	180(SN) +
Spare Tyre Carrier	Best	384.60 -
Spare Tyre Carriers Lock Screw.	Best	58.20 -
Rees Exhaust Pipe	Best	591.40 -
Rees Exhaust Pipe Mounting.	mm	35.40 +
Rees Exhaust Pipe Gasket	mm	34.20 -
Centre Exhaust Pipe.	Rees	1829.10 +

25551.50 SN 2140

19/63.62

GBK3771G.

Panel Beating (Front)	1200 800
Spray Painting (Front)	1200 1000.
Wiring (Front)	50 30
To spray tuff coat (Front)	150 60
To remove condenser and to top up air con gas	120 60
To remove radiator and to top up coolant	120 60
Panel Beating (Rear)	2500 2000
Spray Painting (Rear)	2200 1600
Wiring (Rear)	100 30
To spray tuff coat (Rear)	300 200
To rear upholstery and carpentry furniture	300 250
To remove reverse sensor	100 50
To remove rear camera.	100 50
To remove exhaust pipe (rear and centre)	300 80
To transfer tailgate fittings	150 80.
To replace tailgate g/l's	180 120
Towing Fees.	60 ✓
Total: 2783.62	
h/s: 22.2K.	
21 Days.	
(22.2K)	