



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: S1M03LP2

Date: 08th Mar 2022

Our Ref: CS3/ASM21011562/Tvy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn: Chan Kian Chuan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMQ 8898E

INSURED VEHICLE: SLC 9082X

ACCIDENT DATE: 06/11/2021

We thank you for your instruction on 10/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMQ 8898E from M/s WG Appraisal Services.
- b) Singapore Accident Statement of Vehicles SMQ 8898E and SLC 9082X.
- c) Police Report of Vehicles SLC 9082X.
- d) Final Repair Bill of SMQ 8898E from M/s Max Motors.
- e) Colour damaged vehicle photographs of SMQ 8898E.

Pre-Repair Inspection Date : 12/11/2021 at M/s Max Motors, 1 Kaki Bukit Ave 6 #01-98, Singapore 417883.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMQ 8898E
Make & Model	: Mercedes Benz E 250 Sedan (R17)
Year of Registration	: 2015
Chassis Number	: WDD2120362B141529
Engine Capacity	: 1991 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.