



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711			Ref: CS3/GRB21009280/Rf3e2-1	
			Date: 09/02/2022	
			Code: GRB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLS 2588R	Veh. Inspected	SJF 1474J	
Policy No.	D21MFL0000447	Coverage (\$)	0.00	
Claim No.	MFL2021D0003849	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	14/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi LANCER 2.0L	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JMYSTCY4A8U001180	Colour	BLACK	
Odometer	217642 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	TOYO	6 mm	
L/H Front Tyre	205/60 R16	TOYO	6 mm	
R/H Rear Tyre	205/60 R16	TOYO	6 mm	
L/H Rear Tyre	205/60 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/09/2021	Inspection Date	03/09/2021	
Survey held at	FIX AUTO PTE LTD 5 SOON LEE STREET, #01-61, PIONEER POINT, SINGAPORE 627607			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	