

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122000530/EVF3N2**Date:** 10/02/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SJS4859U**Insured Vehicle No :** XE5119Z

Date of Loss: 12/01/2022

Nature of Claim:

TP

Claim No: CDMFG22000075

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJS4859U**

Make & Model: TOYOTA COROLLA ALTIS, 1.8 (A)

Engine No: 3ZZ4923494

Reg. Date: 19/08/2009 (Man. Year: 2009)

Chassis No: MR053ZEE106152399

Colour: Beige

Odometer: 163183 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15

Rear Tyre Size: 195/65R15

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,402.00	4,353.75	4,048.25	48.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,960.00	2,310.00	650.00	21.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,362.00	6,663.75	4,698.25	41.35
Approved Total (Overridden) (S\$)		5,350.00		
Nett Amount (S\$)	11,362.00	5,350.00	6,012.00	52.91

INSPECTION

Date of Assignment: 14/01/2022

Date Inspected: 14/01/2022

Inspected At:

399J WOODLANDS ROAD

SINGAPORE 678008

REPAIRER: CAR PRO AUTO

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Feb 2022)
Parts:	143	TOYOTA COROLLA ALTIS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS4859U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	625.00 FL	*482.00 FL
2	2		*REAR BUMPER SIDE RETAINER	Broken	150.00 FL	*150.00 FL
3	1		*REAR BUMPER FASTENERS	Broken	20.00 FL	*20.00 FL
4	2		*REAR BUMPER REFLECTOR LAMP	Not Necessary	140.00 FL	*- FL
5	1		*BOOTLID	Dented	880.00 FL	*794.00 FL
6	1		*BOOTLID INNER TRIM BOARD	Not Necessary	288.00 FL	*- FL
7	1		*SET BOOTLID INNER TRIM BOARD FASTENERS	Not Necessary	25.00 FL	*- FL
8	1		*BOOTLID LOGO EMBLEM	Necessary	75.00 FL	*75.00 FL
9	1		*BOOTLID ALTIS EMBLEM	Necessary	65.00 FL	*65.00 FL
10	1		*BOOTLID COROLLA EMBLEM	Necessary	65.00 FL	*65.00 FL
11	1		*BOOTLID INNER LOCK	Bent	185.00 FL	*185.00 FL
12	1		*BOOTLID WEATHERSTRIP	Torn	255.00 FL	*195.00 FL
13	2		*BOOTLID HINGE	Repair	178.00 FL	*- FL
14	2		*BOOTLID STOPPER	Not Necessary	60.00 FL	*- FL
15	1		*BOOTLID CABLE	Not Necessary	105.00 FL	*- FL
16	1		*BOOTLID CHROME GARNISH	Broken	310.00 FL	*254.00 FL
17	1		*SET BOOTLID GARNISH CLIPS	Not Necessary	20.00 FL	*- FL
18	2		*BOOTLID LAMP LH & RH	Broken	600.00 FL	*600.00 FL
19	2		*REAR NUMBER PLATE LAMP	Not Necessary	160.00 FL	*- FL
20	1		*REAR AIR VENT	Not Necessary	165.00 FL	*- FL
21	2		*TAIL LAMP LH & RH	Broken	1,080.00 FL	*930.00 FL
22	2		*SET LH & RH TAILLAMP FASTENERS	Not Necessary	20.00 FL	*- FL
23	2		*LH & RH TAILLAMP BASE PANEL	Not Necessary	225.00 FL	*- FL
24	1		*REAR END PANEL	Dented	690.00 FL	*571.00 FL
25	1		*REAR END PANEL TOP GARNISH	Broken	255.00 FL	*255.00 FL
26	1		*SET REAR END PANEL TOP GARNISH FASTENERS	Not Necessary	25.00 FL	*- FL
27	1		*SPARE TYRE PANEL	Not Necessary	850.00 FL	*- FL
28	1		*SPARE TYRE PANEL BOARD	Not Necessary	320.00 FL	*- FL
29	2		*REAR RH & LH FENDER INNER TRIM	Not Necessary	800.00 FL	*- FL
30	1		*SET REAR RH & LH FENDER INNER TRIM CLIPS	Not Necessary	35.00 FL	*- FL
31	1		*REAR RH FENDER	Dented	1,080.00 FL	*804.00 FL
32	1		*REAR RH FENDER INNER SHIELD	Not Necessary	85.00 FL	*- FL
33	1		*REAR RH FENDER INNER SHIELD CLIPS	Not Necessary	20.00 FL	*- FL
34	1		*EXHAUST MUFFLER	Not Necessary	680.00 FL	*- FL
35	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*30.00 FS
36	1		*SPARE TYRE PANEL SEALANT	Not Necessary	60.00 FS	*- FS
37	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
38	1		*SPARE TYRE PANEL INSULATOR	Not Necessary	120.00 FS	*- FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,036.00	5,715.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,634.00	1,361.25
Total Parts (\$\$)	8,402.00	4,353.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAYING OF AFFECTED AREAS	New	1,200.00	1,000.00
2	CARRY OUT BODY CAVITY PRESERVATION	New	80.00	30.00
3	TO REMOVE & REPLACED DAMAGED PARTS INCLUDING STRAIGHTENING & REPOSITIONING REPLACEMENT PARTS & PANEL BEAT	New	1,200.00	1,000.00
4	CHECK WIRING	New	40.00	30.00
5	REMOVE & REFIX REVERSE SENSOR	New	60.00	30.00
6	REMOVE AND REINSTALL BOOTLID COMPONENTS	New	80.00	50.00
7	REMOVE & REINSTALL REAR BOOT UPHOLSTERY	New	80.00	50.00
8	REMOVE AND REINSTALL REAR EXHAUST MUFFLER	New	100.00	0.00
9	REMOVE AND REINSTALL REAR WINDSCREEN	New	120.00	120.00
Gross Labour Cost (\$\$)			2,960.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >