

ASS. REC. BY:

REF:

CS/EG/22000530/EF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: XE 5119Z

Policy No. _____

Claims No. CDMFG22000075

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJSA859U Yr Regn: 19/8/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Altis c.c. 1598

Colour: Beige A/C: Insured / Std / NI / NA

Sp. Reading: 163183 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MRO53ZEE106152399

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 12/1/22 D.O.I. 14/1/22

Survey held at Car Pro

Des. of Damages: Frt (Rear) O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/2/22 LS \$5350 confirmed by email (red 6012, 53%)

Date/Time, File Pass to?

: Prell. Report

1)

: Final Report

Date/Time, File Return to?

2) 8/2/22-typist

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS. SI

Photos

Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

Report Format: Merimen

Lump Sum / L.B.F. (\$ 5350)

Adjustment of Spare Parts Costs for Repairs SJS 4859U
TOYOTA ALTIS

Item	Qty	Vehicle parts description	\$
1	1	Rear bumper / 00	625.00
2	2	rear bumper side retainer / BR	150.00
3	1	rear bumper fasteners / BR	20.00
4	2/1	rear bumper reflector lamp (RH) ?	140.00
5	1	bootlid / 00	880.00
6	1	bootlid inner trim board X	288.00
7	1set	bootlid inner trim board fasteners X	25.00
8	1	bootlid logo emblem / MC	75.00
9	1	bootlid altis emblem / MC	65.00
10	1	bootlid corolla emblem / MC	65.00
11	1	bootlid inner lock ?	185.00
12	1	bootlid weatherstrip ?	255.00
13	2	bootlid hinge X R	178.00
14	2	bootlid stopper X	60.00
15	1	bootlid cable X	105.00
16	1	bootlid chrome garnish / BR	310.00
17	1set	bootlid garnish clips X	20.00
18	(2)	bootlid lamp LH & RH / BR	600.00
19	2	rear number plate lamp X	160.00
20	1	rear air vent ?	165.00
21	(2)	tail lamp LH & RH / BR	1080.00
22	2set	LH & RH taillamp fasteners X	20.00
23	2	LH & RH taillamp base panel X	225.00
24	1	rear end panel ?	690.00
25	1	rear end panel top garnish ?	255.00
26	1set	rear end panel top garnish fasteners ?	25.00
27	1	spare tyre panel X	850.00
28	1	spare tyre panel board X	320.00
29	2	rear RH & LH fender inner trim X	800.00
30	1set	rear RH & LH fender inner trim clips X	35.00
31	1	rear RH fender / 00	1080.00
32	1	rear RH fender inner shield X	85.00
33	1	rear RH fender inner shield clips X	20.00
34	1	exhaust muffler X	680.00
			10536.00
Less 25%			2634.00
			<u>7902.00</u>
Special nett item			
1	1	rear end panel sealant ?	60.00
2	1	spare tyre panel sealant X	60.00

3	1	Reverse sensor	200.00
4	1	spare tyre panel insulator	120.00
5	1	rear windscreen sealant	60.00
			<u>500.00</u>

Adjustment of Labour Costs for Repairs

Spraying of affected areas	1200.00	1000
Carry out body cavity preservation	80.00	30
To remove & replaced damaged parts including straightening & repositioning replacement parts & panel beat	1200.00	1000
Check wiring	40.00	30
Remove & refix reverse sensor	60.00	30
remove and reinstall bootlid components	80.00	50
Remove & reinstall rear boot upholstery	80.00	30 50
remove and reinstall rear exhaust muffler	100.00	X
remove and reinstall rear windscreen	120.00	✓
TOTAL	2960.00	

Steve (LKK)
14/1/22, 4pm

Whe L
L/S
by M/Ly
8 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: