



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM22000531/Aea3q2 Date: 11/04/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJJ 1962X	Veh. Inspected	SKM 1972P	
Policy No.	GA594335	Coverage (\$)	0.00	
Claim No.	S2M03R11	Excess (\$)	0.00	
Assign From		Assign Date	14/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY HYBRID	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053FK4000012258	Colour	WHITE	
Odometer	269180 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	NEUTON	6 mm	
L/H Front Tyre	215/55 R17	NEUTON	6 mm	
R/H Rear Tyre	215/55 R17	NEUTON	6 mm	
L/H Rear Tyre	215/55 R17	NEUTON	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2022	Inspection Date	14/01/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	