

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000532/EQF3N2**Date:** 01/06/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00131312100

Claimant Vehicle No : GBK4875J **Insured Vehicle No :** SCJ6632Z

Date of Loss: 28/12/2021 Nature of Claim: TP Claim No: SNM21D207652/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK4875J**

Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25067300B

Reg. Date: 13/08/2020 (Man. Year: 2019) Chassis No: JN1MC2E26Z0032020

Colour: Red Odometer: 46138 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195R15C Rear Tyre Size: 195R15C

Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm

Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,909.30	695.00	3,214.30	82.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	460.00	2,420.00	84.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,789.30	1,155.00	5,634.30	82.99
+ GST 7.00/7.00% (S\$)	475.25	80.85	394.40	82.99
Nett Amount (S\$)	7,264.55	1,235.85	6,028.70	82.99

INSPECTION

Date of Assignment: 14/01/2022

Date Inspected: 18/03/2022 Inspected At: Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise Building
Singapore 508775

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 01 Jun 2022)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBK4875J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	496.00 FL	*- FL
2	2		*FRONT BUMPER RETAINER LH/RH	Not Necessary	386.00 FL	*- FL
3	1		*FOG LAMP COVER LH	Not Necessary	105.00 FL	*- FL
4	1		*HEADLAMP ASSY LH	Cut	750.00 FL	*550.00 FL
5	1		*HEADLAMP BRACKET LH	Not Necessary	28.00 FL	*- FL
6	1		*LH FRONT DOOR	Repair	1,794.00 FL	*- FL
7	2		*LH FRONT DOOR HINGE	Not Necessary	170.00 FL	*- FL
8	1		*LH FRONT DOOR CHECKER	Not Necessary	140.00 FL	*- FL
9	1		*STEP GARNISH LH	Not Necessary	108.00 FL	*- FL
10	1		*FRONT BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
11	1		*DOOR CO.REG STICKER	Not Necessary	30.00 FS	*- FS
12	1		*DOOR ADVERTISEMENT STICKERS	Necessary	250.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,307.00	750.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	397.70	55.00
Total Parts (\$\$)	3,909.30	695.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT,REPAIR ON LH FRONT PANEL AND REPLACE DAMAGED PARTS	New	1,500.00	200.00
2	TO CHECK AND RECTIFY LIGHTING AND WIRE HARNESS	New	80.00	30.00
3	TO SPRAY PAINT LH FRONT DOOR,FRONT BUMPER AND AFFECTED AREAS	New	1,000.00	200.00
4	TO TRANSFER LH DOOR PARTS AND MECHANISMS TO NEW DOOR	New	150.00	0.00
5	TO APPLY RUST PROOFING ON REPAIR AND REPLACE PANELS	New	150.00	30.00
			Gross Labour Cost (\$)	2,880.00
				460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >