

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 23 Mar 2022

## **Preliminary Advice**

Insured : SCJ6632Z  
Vehicle No  
TP Vehicle : GBK4875J Accident Date : 28/12/2021  
No  
Make : NISSAN NV350 Assignment Date : 14/01/2022  
Date of : 18/03/2022 Est. Duration of : 3  
Inspection Repair  
Inspection At : EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD (HQ)  
56 LOYANG WAY #06-07, LOYANG ENTERPRISE BUILDING  
SINGAPORE 508775

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,789.30
Revised Amount	:S\$	1,365.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,365.00

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.