

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122000537/DTF3N2**Date:** 28/04/2022REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : FBB2433L**Insured Vehicle No :** YN4069L

Date of Loss: 10/01/2022

Nature of Claim:

TP

Claim No: CDMCG22000068

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBB2433L**

Make & Model: HONDA CB 400 F3WYB, 399cc (M)

Engine No: NC23E3100550

Reg. Date: 23/01/2007 (Man. Year: 2006)

Chassis No: JH2NC39946M200520

Colour: Multi-colour

Odometer: 0 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70R17

Rear Tyre Size: 160/60R17

Front Left Side: Pirelli 2 mm

Rear Left Side: Pirelli 2 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,146.00	1,827.00	3,319.00	64.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	250.00	500.00	66.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,896.00	2,077.00	3,819.00	64.77
Approved Total (Overridden) (S\$)		1,650.00		
Nett Amount (S\$)	5,896.00	1,650.00	4,246.00	72.01

INSPECTION

Date of Assignment: 14/01/2022

Date Inspected: 17/01/2022 Inspected At:

Sg 98 Motor Pte Ltd (HQ)

BLK 4001 ANG MO KIO INDUSTRIAL PARK 1

#01-21

Singapore 569622

Estimated Period of Repair: 3.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Apr 2022)	
Parts:	N/A	HONDA CB 400 F3WYB 399cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBB2433L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*YOSHIMURA EXHAUST PIPE	Dented	1,600.00 FL	*1,200.00 FL
2	1		*REAR PILLION FOOTREST RH	Cut	75.00 FL	*75.00 FL
3	1		*FOOTREST BRACKET	Broken	240.00 FL	*240.00 FL
4	1		*EXHAUST SLIDER RH	Cut/Bent	250.00 FL	*125.00 FL
5	1		*SET REAR SHOCK ABSORBER-CHROME	Not Necessary	2,200.00 FL	*- FL
6	1		*SET FRAME SLIDER	N/s Cut/O/s Not Necessary	380.00 FL	*190.00 FL
7	1		*SET HAND GUARD	N/s Cut/O/s Not Necessary	250.00 FL	*125.00 FL
8	1		*HANDLE BAR	Not Necessary	170.00 FL	*- FL
9	1		*GEAR PEDAL	Not Necessary	110.00 FL	*- FL
10	1		*GEAR PEDAL RUBBER	Not Necessary	90.00 FL	*- FL
11	1		*REAR LH PILLION FOOTREST	Cut	75.00 FL	*75.00 FL
12	1		*DECAL STICKER	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,690.00	2,030.00
- List Item Discount on L Items 10.00/10.00% (\$)	544.00	203.00
Total Parts (\$)	5,146.00	1,827.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REPLACE PARTS,ALIGN & ETC & REPLACE EXHAUST PIPE,SLIDER ETC	New	350.00	250.00
2	REMOVE & REPLACE REAR SHOCK ABSORBER	New	150.00	0.00
3	PUTTY & TOUCH UP PAINT	New	250.00	0.00
Gross Labour Cost (\$)			750.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >