

001/1/13 wel
ASS. REC. BY: *Ram*

REF:

CS/EH12200543/Riv3

369K

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No. **SHB 1169K**
at Workshop m/s **STRIDES**
of **60, Woodlands Rd, Pk 64**
Insured **SLF 8779K ER60**
Policy No. _____
Claims No. **CDMPG22000079**
Sum Insured _____ Excess _____
(Client's Record)
Make of Veh _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value _____
QAC Accident Report Consistent? Yes or No _____
QAC / PR Seen Consistent? Yes or No _____
Est. Repairs days Res Yes or No _____
Lett. Sum % 3 Val Yes or No _____

CA / REV / REP / 24 HRS

Date _____ Person Contacted _____

Vehicle IN / OUT

Date / Time Action / Instruction

Veh No. **SHB 1169K** Yr Regd. **2021/1544**
Type: M. Car / M. Cycle / Bus / Van / Lorry / ~~Truck~~ Prime Mover /
Truck / Trailer or _____
Make: **M.A / M.H.S BU EXCITE** cc _____
Colour **Green** A/C: Insured / Std / NI / NA
Sp. Reading **22271** T/Radio: Insured / Std / NI / NA
Eng No. _____
C No. **LSJE 24038M 6051341**
Gen. Cond: Good / ~~Poor~~ / Poor / Burnt
Steering: ~~In order~~ / Jammed / Leaked / Burnt or _____
Brake: ~~In order~~ / Jammed / Leaked / Burnt or _____
Mod: ~~Nil~~ / S/Rim / STD A/Rim or _____
Tyre Size: F: **205/60R16**
R: _____
~~BS POUN~~ / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	13/01/22	D.O.I.	17/01/22

Survey held at **STRIDES**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

25/2/22 Rasul informed final fig \$5361.02 (red 27603.90, 83%)

Date/Time: File Pass to? ☐ Preli. Report

1) ☐ Final Report

Date/Time: File Return to?

2) 1/3/22-typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

Transportation

) \$ + RES \$

) Photos

) Others

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Assessment (\$

Report Format: Merimen

Lump Sum / I.B.I: (\$ 5361.02

Case Details

Case Reference Number : TAX/01/22/2022
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1169K

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-17216-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : ERGO Insurance Pte Ltd
 Accident Date and Time : 12/01/2022 07:05 PM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			WINDOW ASM-REAR (WINDSCREEN REAR)	1	323.44	323.44	10.00	291.10	Replace	1	291.10	Replace	an ✓
Standard	Main			SEALANT W/SCREEN	2	37.00	74.00	0.00	74.00	Replace	2	74.00	Replace	an ✓
Standard	Main			SPOILER ASM-R/END	1	466.96	466.96	10.00	420.26	Replace	0	0.00	Not Give	Xan
Standard	Main			LAMP ASM-HIGH MT STOP	1	150.08	150.08	10.00	135.07	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL ASM-QTR OTR TR - LH	1	45.04	45.04	10.00	40.54	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL ASM-QTR OTR TR - RH	1	45.04	45.04	10.00	40.54	Replace	0	0.00	Not Give	Xan
Standard	Main			PLUG-BODY HOLE	2	1.66	3.32	10.00	2.99	Replace	0	0.00	Not Give	Xan
Standard	Main			STRIKER ASM-L/GATE LAT	1	17.16	17.16	10.00	15.44	Replace	0	0.00	Not Give	Xan
Standard	Main			LATCH ASM-L/GATE	1	139.36	139.36	10.00	125.42	Replace	0	0.00	Not Give	Xan
Standard	Main			COVER-L/GATE LAT	1	6.86	6.86	10.00	6.17	Replace	0	0.00	Not Give	Xan
Standard	Main			SWITCH-L/GATE OPEN	1	30.68	30.68	10.00	27.61	Replace	0	0.00	Not Give	Xan
Standard	Main			HINGE ASM-L/GATE - LH	1	30.88	30.88	10.00	27.79	Replace	0	0.00	Not Give	Xan
Standard	Main			HINGE ASM-L/GATE - RH	1	30.88	30.88	10.00	27.79	Replace	0	0.00	Not Give	Xan
Standard	Main			STRUT ASM-L/GATE - LH	1	52.52	52.52	10.00	47.27	Replace	0	0.00	Not Give	Xan
Standard	Main			STRUT ASM-L/GATE -RH	1	52.52	52.52	10.00	47.27	Replace	0	0.00	Not Give	Xan

Total Spare Part Cost 19,764.99

Surveyor Total 3,320.85

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0.00

Final Spare Part Cost 19,764.99

Final Sur Total 3,320.85

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			BUFFER-L/GATE(The tail door side)	2	4.16	8.32	10.00	7.49	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL-L/GATE UPR TR	1	10.30	10.30	10.00	9.27	Replace	0	0.00	Not Give	Xan
Standard	Main			COVER-L/GATE T/PNL	2	1.56	3.12	10.00	2.81	Replace	0	0.00	Not Give	Xan
Standard	Main			HARNESS ASM-L/GATE LINK WRG	1	267.80	267.80	10.00	241.02	Replace	0	0.00	Not Give	Xan
Standard	Main			WEATHERSTRIP-L/GATE	1	73.52	73.52	10.00	66.17	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL-T/LP TR - RH	1	20.90	20.90	10.00	18.81	Replace	0	0.00	Not Give	Xan
Standard	Main			BRACKET ASM-RR BPR FASCIA SI - LH	1	29.84	29.84	10.00	26.86	Replace	0	0.00	Not Give	Xan
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL ASM-RR END	1	708.66	708.66	10.00	637.79	Replace	0	0.00	Not Give	Xan
Standard	Main			LAMP ASM-TAIL(LID SI) - RH	1	407.68	407.68	10.00	366.91	Replace	0	0.00	Check	?
Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0.00	Check	?
Standard	Main			PANEL ASM-R/CMPT TAIL LAMP - RH	1	167.44	167.44	10.00	150.70	Replace	0	0.00	Not Give	Xan
Standard	Main			LINER ASM-RR W/H PNL - RH	1	85.48	85.48	10.00	76.93	Replace	0	0.00	Not Give	Xan
Standard	Main			CARPET ASM-R/CMPT FLR PNL	1	149.66	149.66	10.00	134.69	Replace	0	0.00	Not Give	Xan
Standard	Main			COVER-R/CMPT SILL T/PNL	1	2.40	2.40	10.00	2.16	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL ASM-R/CMPT SI TR - RH	1	235.24	235.24	10.00	211.72	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL ASM-R/CMPT SI TR - LH	1	223.92	223.92	10.00	201.53	Replace	0	0.00	Not Give	Xan
Standard	Main			DOOR ASM-RR SI - LH	1	2,185.04	2,185.04	10.00	1,966.54	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL ASM-R/CMPT TAIL LAMP - LH	1	167.24	167.24	10.00	150.52	Replace	0	0.00	Not Give	Xan
Standard	Main			LINER ASM-RR W/H PNL - LH	1	83.72	83.72	10.00	75.35	Replace	0	0.00	Not Give	Xan
Standard	Main			LAMP ASM-TAIL(BODY SI) - RH	1	764.08	764.08	10.00	687.67	Replace	0	0.00	Not Give	Xan
Standard	Main			PANEL-T/LP TR - RH	1	20.90	20.90	10.00	18.81	Replace	0	0.00	Not Give	Xan
Total Spare Part Cost									19,764.99	Surveyor Total				3,320.85
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				0.00
Final Spare Part Cost									19,764.99	Final Sur Total				3,320.85

Others

Lump Sum / I.B.I. (\$)

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			PANEL-BODY SI OTR RR FENDER - RH	1	977.08	977.08	10.00	879.37	Replace	0	0.00	Not Give	X97
Standard	Main			STICKER ELECTRIC (LOGO)	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Give	X97
Standard	Main			WINDOW ASM-QTR - RH	1	251.48	251.48	10.00	226.33	Replace	0	0.00	Not Give	X97
Standard	Main			LAMP ASM-TAIL(BODY SI) - LH	1	764.08	764.08	10.00	687.67	Replace	0	0.00	Not Give	X97
Standard	Main			PANEL-T/LP TR - LH	1	20.90	20.90	10.00	18.81	Replace	0	0.00	Not Give	X97
Standard	Main			PANEL-BODY SI OTR RR FENDER - LH	1	1,201.52	1,201.52	10.00	1,081.37	Replace	0	0.00	Not Give	X97
Standard	Main			STICKER ELECTRIC (LOGO)	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Give	X97
Standard	Main			RAIL SUB ASM-R/CMPT SI -RH	1	965.54	965.54	10.00	868.99	Replace	0	0.00	Not Give	X97
Standard	Main			PANEL ASM-RR W/H INR -LH	1	709.38	709.38	10.00	638.44	Replace	0	0.00	Not Give	X97
Standard	Main			PANEL ASM-RR W/H INR -RH	1	663.52	663.52	10.00	597.17	Replace	0	0.00	Not Give	X97
Standard	Main			PANEL ASM-L/GATE LWR TR	1	167.34	167.34	10.00	150.61	Replace	0	0.00	Not Give	X97
Standard	Main			PANEL ASM-RR END	1	708.66	708.66	10.00	637.79	Replace	0	0.00	Not Give	X97
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Give	X97
Standard	Main			PANEL ASM-R/FLR R/SEAT	1	2,814.00	2,814.00	10.00	2,532.60	Replace	0	0.00	Not Give	X97
Standard	Main			LAMP ASM-TAIL(LID SI) - RH	1	407.68	407.68	10.00	366.91	Replace	0	0.00	Check	?
Standard	Main			PLATE ASM-RR LIC PLT	1	96.40	96.40	10.00	86.76	Replace	1	86.76	Replace	OK
Standard	Main			LAMP ASM-TAIL(LID SI) - LH	1	407.68	407.68	10.00	366.91	Replace	0	0.00	Not Give	X97
Standard	Main			NUMBER PLATE	1	35.00	35.00	0.00	35.00	Replace	1	35.00	Replace	OK
Standard	Main			NUMBER PLATE FRAME	1	25.00	25.00	0.00	25.00	Replace	1	25.00	Replace	OK
Standard	Main			STICKER STRIDES TAXI WITH (GO GREEN LOGO)/ (TAIL GATE)	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	OK
Standard	Main			STICKER DECAL 6555 8888 (TAIL GATE)	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	OK
Standard	Main			SENSOR-RR PARK DIST CONT	3	65.00	195.00	10.00	175.50	Replace	0	0.00	Check	?
Total Spare Part Cost									19,764.99	Surveyor Total 3,320.85				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0.00				
Final Spare Part Cost									19,764.99	Final Sur Total 3,320.85				

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval				Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
Standard	Main			TAIL GATE ASM-LIFT	1	1,928.26	1,928.26	10.00	1,735.43	Replace	1	1,735.	Replace	✓	bt ✓
Standard	Main			EMBLEM ASM-RR LIC PLT (MG)	1	62.92	62.92	10.00	56.63	Replace	1	56.63	Replace	✓	nu ✓
Standard	Main			EMBLEM ASM-L/GATE (MG5 SW)	1	21.84	21.84	10.00	19.66	Replace	1	19.66	Replace	✓	nu ✓
Standard	Main			EMBLEM ASM-L/GATE (SW EV)	1	33.90	33.90	10.00	30.51	Replace	1	30.51	Replace	✓	nu ✓
Standard	Main			COVER-RR TOW HOOK OPG	1	6.76	6.76	10.00	6.08	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			LAMP ASM-RR FOG - RH	1	189.08	189.08	10.00	170.17	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			LAMP ASM-RR FOG - LH	1	36.30	36.30	10.00	32.67	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0.00	Check	✓	?
Standard	Main			SCRIVET-RR BPR FASCIA	10	0.84	8.40	10.00	7.56	Replace	10	7.56	Replace	✓	nu ✓
Standard	Main			BOLT/SCREW-FRT W/H LNR RET	12	0.52	6.24	10.00	5.62	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			NUT-RR BPR FASCIA BRKT	10	0.94	9.40	10.00	8.46	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			NUT-RR BPR FASCIA	2	0.52	1.04	10.00	0.94	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			CLIP-RR BPR FASCIA	4	1.24	4.96	10.00	4.46	Replace	4	4.46	Replace	✓	nu ✓
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	1	12.90	12.90	10.00	11.61	Replace	1	11.61	Replace	✓	nu ✓
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	1	12.90	12.90	10.00	11.61	Replace	1	11.61	Replace	✓	nu ✓
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - RH	1	12.80	12.80	10.00	11.52	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - LH	1	12.80	12.80	10.00	11.52	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - RH	1	46.08	46.08	10.00	41.47	Replace	0	0.00	Not Give	✓	Xn
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH	1	46.08	46.08	10.00	41.47	Replace	0	0.00	Not Give	✓	Xn

Total Spare Part Cost 19,764.99

Surveyor Total 3,320.85

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0.00

Final Spare Part Cost 19,764.99

Final Sur Total 3,320.85

J1/2022, 16:02

https://vacswb.smrt.com.sg/Estimation.aspx

I Veh No:

SLB 17800

Yr Regn:

2017/84

SMRT Recommendation

Surveyor Approval

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - LH	1	13.20	13.20	10.00	11.88	Replace	1	11.88	Replace	mu
Standard	Main			FINISHER-RR BPR - RH	1	47.42	47.42	10.00	42.68	Replace	0	0.00	Not Give	fan
Standard	Main			FINISHER-RR BPR - LH	1	47.42	47.42	10.00	42.68	Replace	0	0.00	Not Give	fan
Standard	Main			BRACKET ASM-RR BPR FASCIA SI - RH	1	29.84	29.84	10.00	26.86	Replace	0	0.00	Not Give	fan
Standard	Main			BRACKET ASM-RR BPR FASCIA SI - LH	1	29.84	29.84	10.00	26.86	Replace	0	0.00	Not Give	fan
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	682.63	Replace	de
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	1	207.61	Replace	see
Total Spare Part Cost									19,764.99	Surveyor Total 3,320.85				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 0.00				
Final Spare Part Cost									19,764.99	Final Sur Total 3,320.85				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	4,800.00	500.00	
Total:			4,800.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR PANEL	230.00	0.00	fan
2	Main	TO RESPRAY REAR SPARE TYRE PANEL	230.00	0.00	fan
3	Main	TO RESPRAY REAR FENDER LH	428.00	0.00	fan
4	Main	TO RESPRAY REAR FENDER RH	428.00	0.00	fan
5	Main	TO RESPRAY TAIL GATE	428.00	220.00	
6	Main	TO RESPRAY REAR SPOILER	230.00	0.00	fan
7	Main	TO RESPRAY REAR MEMBER, LH	230.00	0.00	fan

01/2022, 16:02

https://vacsweb.smrt.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
8	Main	TO RESPRAY REAR MEMBER,RH	230.00	0.00 X17	
9	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	230.00	0.00 X17	
10	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	230.00	0.00 X17	
11	Main	TO RESPRAY TAIL LAMP PANEL LH	230.00	0.00 X17	
12	Main	TO RESPRAY TAIL LAMP PANEL RH	230.00	0.00 X17	
13	Main	TO RESPRAY REAR BUMPER	428.00	220	
Total:			3,782.00	440.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 X17	
2	Main	ISOLATED OF (EV) (NET)	150.00	150.00	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0 X17	
4	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0 X17	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	60	
6	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	40	
7	Main	TO REMOVE / REFIT SEAT	120.00	0 X17	
8	Main	TO ALIGN CHASSIS	350.00	0 X17	
9	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	350.00	350.00	
10	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	
11	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0 X17	
12	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0 X17	
13	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
14	Main	TO REMOVE AND REFIX REAR WINDSCREEN	120.00	120.00	
Total:			2,490.00	930.00	

To Inspect Vehicle No: 3110117

1/2022, 15:02

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	19,764.99	3,320.85
Total Labour Cost	4,800.00	500.00
Total Spray Painting	3,782.00	440.00
Other	2,490.00	930.00
Overall Total	30,836.99	5,190.85
Lump Sum Repair Option		☐
Lump Sum Total	0.00	5,190.85
Surveyor Approved Amount		5,190.85
No of Repair Days*	11	5
Remarks		PART BY PART REPAIR / RESURVEY BEFORE PAINT PHOTO /
Surveyor Name		Rasul
Signature		
		Save Clear
Survey Date	17/01/2022	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/01/2022 15:47 (SGT)
Date of Accident	13/01/2022 03:05 (SGT)
Exact Location of Accident	Bukit Batok Ave 1, Singapore
Additional Location Information	JUNCTION OF BUKIT BATOK AVE 1 / BUKIT BATOK AVE 6
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1169K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	Strides Taxi Pte Ltd
Company Reg No	1XXXXX369K
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	MG
Model	MG5
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1800

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097466MFSH
Cover Note Number	-

DRIVER

Name of Driver	CHAN KHAI MUN
NRIC No	SXXXX709G

Date of Birth	11/04/1960
Occupation	Outdoor
Date Of Driving Pass	18/10/1978
Driving experience	43 YEARS AND 3 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	AUTO-SVCS-TARC@SMRT.COM.SG
Address	11
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

ON 13/01/22 AT ABOUT 0305HRS. I WAS STATIONARY AT JUNCTION OF BUKIT BATOK AVE 1 & BUKIT BATOK EAST AVE 6. SUDDENLY A VEHICLE (SLF8779K) HIT ONTO REAR PORTION OF MY VEHICLE.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE TOO BIG
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF8779K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TEO CHIN LIAN
Contact Number	-

Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

Truck / Trailer or

Passenger / WS / IP / RES / OD / RES / EVA / INV / MV

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be cited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

13/1/2022

A. 13/01/22

Witnessed by Reporting Centre Personnel

Sketch Plan

